

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23002070/Kwp3m4	
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date	: 06/03/2023	
	ATTN: HO WINNIE		Code	e: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 7141E	Veh. Inspected	FBH 3603A	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04JNP	Excess (\$)	0.00	
	Assign From	HO WINNIE	Assign Date	23/02/2023	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZ 16	c.c	153	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	ME121C0D2D2023996	Colour	RED / GREY	
	Odometer	99999 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	100/80 R17	PIRELLI	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130/70 R17	PIRELLI	3 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.		BODY.		
5. General Information					
	Accident Date	17/02/2023	Inspect Date / Time	27/02/2023 (12:06 PM)	
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$800				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	2 Wo	rking Days	
Report Ref No. CS3/HSB23002070/Kwp3m4					

Report Ref No. CS3/HSB23002070/Kwp3m4

Inspected By

KONG SENG CHEONG

K.K.LAU CPT(RET)

Licensed Appraiser BEng

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser