

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002073/ANCM4**Date:** 06/07/2023**REFERENCE**

Insured/Claimant:	LIM TENG KHENG, DESMOND	Policy No:	1900164546
Date of Loss:	29/12/2022	Nature of Claim:	OD Claim No: 6992778019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX6611C		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZC31647
Reg. Date:	25/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V6KA103659
Colour:	White	Odometer:	67483 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,873.00	1,853.60	3,019.40	61.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,295.00	3,375.60	3,919.40	53.73
+ GST 8.00/8.00% (S\$)	583.60	270.05	313.55	53.73
Nett Amount (S\$)	7,878.60	3,645.65	4,232.95	53.73

INSPECTION

Date of Assignment:	24/02/2023		
Date Inspected:	24/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
3	2		*REAR WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	36.00 FS	*- FS
5	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	67.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Not Necessary	264.00 FS	*- FS
7	2		*REAR BUMPER REFLECTOR - LH / RH	Not Necessary	92.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	642.00 FS	*- FS
9	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	63.00 FS	*- FS
10	3		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	797.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,873.00	1,853.60
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >