

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002076/AVCE2**Date:** 22/03/2023**REFERENCE**

Insured/Claimant:	MATSUO HIROYUKI	Policy No:	7220147490
Date of Loss:	17/02/2023	Nature of Claim:	OD
		Claim No:	5643336139SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV40A	Engine No:	HIDDEN
Make & Model:	AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A)	Chassis No:	WAUZZZGE8PB013044
Reg. Date:	20/12/2022 (Man. Year: 2022)	Odometer:	2117 km
Colour:	Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$330,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,804.00	330.00	19,474.00	98.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,462.00	2,572.00	20,890.00	89.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,266.00	2,902.00	40,364.00	93.29
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	42,066.00	1,702.00	40,364.00	95.95
+ GST 8.00/8.00% (S\$)	3,365.28	136.16	3,229.12	95.95
Nett Amount (S\$)	45,431.28	1,838.16	43,593.12	95.95

INSPECTION

Date of Assignment:	24/02/2023		
Date Inspected:	24/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$500.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL - LH	Repair	5,168.00 FS	*- FS
2	1		*REAR QUARTER WINDOW - LH	Not Necessary	970.00 FS	*- FS
3	1		*WINDOW PRIMER	Not Necessary	24.00 FS	*- FS
4	1		*REAR DOOR SILL TRIM STRIP - LH	Not Necessary	140.00 FS	*- FS
5	1		*REAR DOOR - LH	Repair	5,085.00 FS	*- FS
6	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	202.00 FS	*- FS
7	1		*REAR DOOR SHELL OUTER SEAL - LH	Not Necessary	175.00 FS	*- FS
8	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	226.00 FS	*- FS
9	1		*REAR DOOR CATCH - LH	Not Necessary	117.00 FS	*- FS
10	1		*REAR DOOR COVER - LH	Not Necessary	485.00 FS	*- FS
11	1		*REAR DOOR WHEEL COVER - LH	Cut	117.00 FS	*117.00 FS
12	1		*REAR WHEEL COVER - LH / RH	N/S Cut	426.00 FS	*213.00 FS
13	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	322.00 FS	*- FS
14	1		*REAR BUMPER SPOILER	Not Necessary	1,442.00 FS	*- FS
15	1		*REAR ALUMINIUM RIM - LH	Not Necessary	2,502.00 FS	*- FS
16	1		*STATIC MIXER	Not Necessary	12.00 FS	*- FS
17	1		*2-PACK EPOXY ADHESIVE	Not Necessary	161.00 FS	*- FS
18	1		*REAR ALUMINIUM POWDER	Not Necessary	651.00 FS	*- FS
19	1		*REAR HARDENER	Not Necessary	232.00 FS	*- FS
20	1		*REAR ALUMINIUM PRIMER	Not Necessary	247.00 FS	*- FS
21	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
22	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
23	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
24	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*SUNDRIES	* Check	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	19,804.00
						330.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	450.00	0.00
3	TO RENEW LHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	0.00
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	0.00
7	TO PLACE THE VEHICLE IN ALUMINIUM BAY	New	1,800.00	0.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	600.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING	New	7,500.00	1,300.00
10	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	0.00
11	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT TEST	New	280.00	0.00
12	TO CARRY OUT DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION ON ACTIVATION	New	480.00	480.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			23,462.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >