



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FD 6997S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT/DISTORTED	145.00	145.00
1	SET HANDLE BAR END BALANCER	ABRADED	44.00	44.00
1	CLUTCH LEVER	BROKEN	23.00	23.00
1	FRONT FENDER	CRACKED	145.00	145.00
1	FRONT RIM	DENTED/WARPED	300.00	300.00
1	FRONT BRAKE DISK	NOT NECESSARY	95.00	-
2	FRONT FORK ASSY L/R	BENT	640.00	640.00
1	STEERING TOP TRIPLE CLAMP	NOT NECESSARY	125.00	-
1	STEERING STEM	BENT/DISTORTED	185.00	185.00
1	STEERING CON & BEARING SET - UPPER	NECESSARY	46.00	46.00
1	STEERING CON & BEARING SET - BOTTOM	NECESSARY	42.00	42.00
1	HEADLAMP BRACKET	NOT NECESSARY	95.00	-
1	FUEL TANK SIDE COVER RH	DENTED/ BRACKETS BROKEN	55.00	55.00
1	FUEL TANK SIDE COVER STICKER	NECESSARY	20.00	20.00
1	GEAR SELECTOR PEDAL	BENT	48.00	48.00
1	REAR SIGNAL LAMP ASSY LH	SCRAPED	22.00	22.00
1	EXHAUST MUFFLER	NOT NECESSARY	650.00	-
1	EXHAUST MUFFLER END CAP	GRAZED/CRACKED	48.00	48.00
1	EXHAUST MUFFLER PROTECTOR	DENTED	42.00	42.00
1	RH SIDE COWL YAMAHA LOGO	NECESSARY	22.00	22.00
1	RH SIDE COWL	ABRADED	55.00	55.00
	LESS 10% DISCOUNT		-284.70	-188.20
			2,562.30	1,693.80
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	15.00	-
			15.00	-
	<u>LABOUR</u>			
	TOWING FEE (2X).		80.00	80.00
	LABOUR CHARGES.		700.00	200.00

Report Ref No. CS3/ASM22007286/Dqy3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING AND LIGHTING.		45.00	30.00
	SPRAY PAINTING.		400.00	250.00
	BODY FRAME REPAIR AND PAINTING.		480.00	200.00
			1,705.00	760.00
GRAND TOTAL			4,282.30	2,453.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS3/ASM22007286/Dqy3m4-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.