

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23002086/KYA3Q2  
**Date:** 18/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220066000
<b>Claimant Vehicle No :</b>	SNH5034L	<b>Insured Vehicle No :</b>	SMD7309P
Date of Loss:	22/02/2023	Nature of Claim:	TP
		Claim No:	3823667036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNH5034L</b>		
Make & Model:	TOYOTA YARIS CROSS, 1.5 HYBRID ACTIVE (2WD) (A)	Engine No:	M15AY461712
Reg. Date:	31/10/2022 (Man. Year: 2022)	Chassis No:	JTDKBAB3301001797
Colour:	Metallic Gold	Odometer:	20093 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,449.25	2,827.80	2,621.45	48.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,390.00	700.00	33.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,539.25</b>	<b>4,217.80</b>	<b>3,321.45</b>	<b>44.06</b>
<b>+ GST 8.00/8.00% (S\$)</b>	603.14	337.42	265.72	44.06
<b>Nett Amount (S\$)</b>	<b>8,142.39</b>	<b>4,555.22</b>	<b>3,587.17</b>	<b>44.06</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,797.22</b>		

INSPECTION

Date of Assignment:	23/02/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	23/02/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,724.00 FL	*1,543.90 FL
2	1		*REAR TAILGATE YARIS EMBLEM	Necessary	60.00 FL	*60.00 FL
3	1		*REAR TAILGATE CROSS EMBLEM	Necessary	60.00 FL	*60.00 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	60.00 FL	*60.00 FL
5	1		*REAR TAILGATE INNER LOCK	Repair	561.00 FL	*- FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	352.00 FL	*352.00 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	393.00 FL	*- FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
9	1		*REAR BUMPER	Buckled	488.00 FL	*417.10 FL
10	1		*REAR BUMPER LOWER LIP	Bent	600.00 FL	*525.50 FL
11	1		*REAR BUMPER ANTENNA SENSOR	Cracked	78.00 FL	*78.00 FL
12	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	108.00 FL	*- FL
13	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	108.00 FL	*- FL
14	1		*REAR END PANEL	Repair	750.00 FL	*- FL
15	1		*REAR END PANEL UPPER COVER	Buckled	381.00 FL	*343.90 FL
16	1		*REAR FLOOR PANEL FOAM TOOLBOX TRAY	Serviceable	161.00 FL	*- FL
17	1		*REAR FLOOR PANEL TOOLBOX TRAY UNDER BOARD	Serviceable	465.00 FL	*- FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
21	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
22	1		*REAR END PANEL JOINT SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*REAR END PANEL UPPER COVER CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,059.00	3,710.40
- List Item Discount on L Items 25.00/25.00% (S\$)	1,609.75	882.60
Total Parts (S\$)	5,449.25	2,827.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	60.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>2,090.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >