

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SMK6057K

Accident Date : 22/2/23

Location : PIE (CHANGI) AFTER TOA PAYOH EXIT

Model: HYUNDAI AD AVANTE

17/4/2019]

Xiao Tong

3P:

SMU4547Z (AIG)

K MIT D84/CMICU 891997

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Delnd</i>	596.70	<i>474</i>	
2	10 pcs	Rear bumper clips <i>Neu</i>		30.00	
3	1 pc	Rear bumper enforcement <i>cmld</i>	383.40		
4	3 pcs	Rear enforcement brackets <i>1 piece dent</i>	110.4	<i>20</i>	
5	2 pcs	Rear o/s & n/s stay bracket <i>1 piece dent</i>	124.8	<i>20</i>	
6	2 pcs	Rear n/s & o/s stay <i>o/s Bent Dented</i>	228.4	<i>114.20</i>	
7	1 pc	Rear bumper lower garnish <i>Cut.</i>	459.60	<i>353</i>	
8	8pcs	Rear bumper lower garnish clips <i>neu</i>		24.00	
9	2pcs	Rear bumper o/s & n/s reflector <i>neu</i>	261.90	<i>x.</i>	
10	2pcs	Rear bumper o/s & n/s retainer <i>Neu Neu</i>	115.20	<i>x.</i>	
11	1 pc	Rear bumper antenna <i>3M</i>	283.70	<i>x</i>	
12	2 pcs	Rear o/s & n/s tail-lamp <i>neu</i>	942.80	<i>x.</i>	
13	1 pc	Rear end panel <i>Repis</i>	591.00	<i>x.</i>	
14	1 pc	Rear end panel inner trim <i>neu</i>	147.80	<i>x</i>	
15	1 pc	Rear undercover <i>neu</i>	85.70	<i>+</i>	
16	1 set	Rear reverse sensor <i>demd.</i>		280.00	<i>200.</i>
17	2pcs	Rear reg. no. plate lamp <i>neu</i>	82.40	<i>+</i>	
18	1 pc	Rear reg. no. plate <i>Ct.</i>		45.00	<i>30</i>
19	1 pc	Rear reg. no. plate bracket <i>Delnd</i>		29.00	
20	1 pc	Reverse sensore wire harness <i>neu</i>		180.00	<i>+</i>
21	1 pc	Rear n/s corner radar <i>Not Nec</i>	1355.20	<i>x.</i>	
22	1 pc	Front bumper <i>Delnd</i>	616.90	<i>485</i>	
23	1 pc	Front bumper enforcement <i>neu</i>	764.50	<i>+</i>	
24	1 pc	Front bumper insulator <i>cmld C.</i>	256.20	<i>110</i>	
25	1 pc	Front bumper lower diffuser <i>Delnd</i>	82.80		
26	2 pcs	Front bumper o/s & n/s retainer <i>neu</i>	70.40	<i>x.</i>	
27	2 pcs	Front bumper o/s & n/s garnish strip (black) <i>3M</i>	66.00	<i>x</i>	
28	2 pcs	Front bumper o/s & n/s bracket <i>neu</i>	86.20	<i>x.</i>	

29	10 pcs	Front bumper clips <i>new</i>		30.00	/
30	1 pc	Front grille <i>cut</i>	678.60	529.	
31	4 pcs	Front grille emblem <i>new</i>	106.50	58.	
32	4 pcs	Front grille clips <i>new</i>		12.00	/
33	1 pc	Front reg. no. plate <i>cut</i>		45.00	30
34	1 pc	Front reg. no. plate bracket <i>cut</i>		29.00	/
35	1 pc	Front reg. no. plate moulding <i>new</i>	80.00	X	
36	2 pcs	Front o/s & n/s head lamp <i>o/s could</i>	2875.60	1432.80	
37	2 pcs	Front o/s & n/s head lamp bracket <i>new</i>	71.30	X	
Sub-Total:			11,523.80	704.00	0.00
			20%	0%	0%
After Less %:			9,219.04	704.00	0.00
Labour					
1		To remove and replace rear damage parts	2,000.00	600.	
2		To spray painting.	1,800.00	600.	
3		To re-seal anti-rust.	100.00	X 30	
4		To check for fault code and resetting	150.00	X	
5		To remove and replace reverse sensor	80.00	50.	
6		To check wiring.	80.00	60.	
Sub-Total:			4,210.00		
Total:			14,133.04		
After Less 20%:			11,306.43		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



AL 8778 1999
24 hr accident call



Adrian Ly
2/s 23/02/23.
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List: 4072.2
Len 20%: 3257.76.
S.N: 414
Labo 1340
total: 5011.76
L/S: HK.