

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002090/RYA3Q2**Date:** 20/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2004251073
Claimant Vehicle No :	SKV636U	Insured Vehicle No :	S1815CD
Date of Loss:	22/02/2023	Nature of Claim:	TP
		Claim No:	202332005673

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV636U		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030409180
Reg. Date:	28/08/2015 (Man. Year: 2015)	Chassis No:	WDD2050402R083891
Colour:	Grey	Odometer:	98534 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,781.61	2,781.61	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,260.00	640.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,681.61	5,041.61	640.00	11.26
+ GST 8.00/8.00% (S\$)	454.53	403.33	51.20	11.26
Nett Amount (S\$)	6,136.14	5,444.94	691.20	11.26
+ Car Rental (5.0 x S\$100.00/day + 8.00% GST) (S\$)		540.00		
Nett Liability (S\$)		5,984.94		

INSPECTION

Date of Assignment:	23/02/2023	
Date Inspected:	24/03/2023 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV636U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,889.77 FS	*1,889.77 FS
2	1		*REAR BUMPER LOWER BLACK TRIM	Cut	283.67 FS	*283.67 FS
3	1		*REAR BUMPER CHROME MOULDING	Necessary	326.71 FS	*326.71 FS
4	10		*RIVET FOR BUMPER	Necessary	53.40 FS	*53.40 FS
5	1		*LH /REAR BUMPER CHROME MOULDING	Necessary	114.03 FS	*114.03 FS
6	1		*RH /REAR BUMPER CHROME MOULDING	Necessary	114.03 FS	*114.03 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,781.61	2,781.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,440.00	960.00
2	RESPRAY REAR BUMPER	New	960.00	800.00
3	USING CENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (S\$)			2,900.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >