

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002108/UVY3Q2**Date:** 15/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00114972200

Claimant Vehicle No : SFN7070G **Insured Vehicle No :** SKP6286M

Date of Loss: 23/02/2023 Nature of Claim: TP Claim No: SNM23D201456/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFN7070G**

Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE SALOON AUTO (A) Engine No: 28291480059469

Reg. Date: 02/04/2020 (Man. Year: 2019) Chassis No: WDD1771872W011875

Colour: Silver Odometer: 33657 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17

Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,820.00	2,025.00	1,795.00	46.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	670.00	1,630.00	70.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,120.00	2,695.00	3,425.00	55.96
+ GST 8.00/8.00% (S\$)	489.60	215.60	274.00	55.96
Nett Amount (S\$)	6,609.60	2,910.60	3,699.00	55.96

INSPECTION

Date of Assignment: 24/02/2023

Date Inspected: 01/03/2023 Inspected At: Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	143	MERCEDES-BENZ A200 1.3 AMG LINE SALOON AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN7070G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
2	1		*REAR BUMPER CHROME	Scratched	290.00 F	*290.00 FL
3	2		*REAR BUMPER EXHAUST CHROME L&R	Serviceable	410.00 F	*- FL
4	2		*REAR BUMPER REFLECTOR L&R	Not Necessary	100.00 F	*- FL
5	1		*REAR BUMPER FASCIA }	Dented / Torn	1,390.00 F	*1,390.00 FL
6	1		*REAR BUMPER TOWING COVER }		130.00 F	*- FL
7	2		*REAR BUMPER SENSOR CENTRE L&R	Serviceable	430.00 F	*- FL
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	500.00 F	*- FL
9	1		*REAR BUMPER LOWER	Distorted	520.00 F	*520.00 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					3,820.00	2,250.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	225.00
Total Parts (\$\$)					3,820.00	2,025.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT ,RENEW ,KNOCKING & WELDING REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	1,080.00	300.00
2	REMOVE & INSTALL REAR BUMPER SENSOR	New	100.00	50.00
3	REMOVE & INSTALL REAR EXHAUST SILENCER ASSY	New	100.00	0.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	680.00	300.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	40.00	20.00
6	DIAGNOSTIC CHECK RESET	New	300.00	0.00
Gross Labour Cost (S\$)			2,300.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >