5/26/23, 5:02 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI23002112/UNY3Q2

26/05/2023 Date:

REFERENCE

No:

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle

FBT3532H

Insured Vehicle No:

YQ881M

Date of Loss: 16/02/2023 Nature of Claim:

TP

CDMCG23000446

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT3532H**

Make & Model: HONDA CBR150R, 150cc Reg. Date: 22/01/2022 (Man. Year: 2019) Engine No:

Odometer:

KC92E1022207

Colour: Grey

Chassis No: MH1KC921XKK025791 0 km

Claim No:

Engine Capacity: Market Value/New Car 149 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 140/70 R17 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,274.00	342.90	931.10	73.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	424.00	260.00	164.00	38.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,698.00	602.90	1,095.10	64.49
+ GST 8.00/8.00% (S\$)	135.84	48.23	87.61	64.49
Nett Amount (S\$)	1,833.84	651.13	1,182.71	64.49

INSPECTION

Date Inspected:

Date of Assignment: 24/02/2023

> NO 6 DEFU LANE 4 27/02/2023 Inspected At:

SINGAPORE 539410

Repairer:Ban Hock Hin Co. Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA **HUEY YON** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 May 2023)

Parts: N/A HONDA CBR150R 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBT3532H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qιy	Part No.	Particulars	Condition	Repairer's	Amount
1		*COVER INNER LH	Cracked	46.00 F	*46.00 FL
1		*COVER TAIL LH	Not Necessary	200.00 F	*- FL
1		*COWLING FRONT LOWER	Cracked	62.00 F	*62.00 FL
1		*COWLING SIDE FRT LH	Cut	45.00 F	*45.00 FL
1		*COWLING UPPER	Repair	306.00 F	*- FL
1		*SET GUARD BALANCER GRIP	Cut	142.00 F	*142.00 FL
1		*SET LAMP SIGNAL FRONT	Cut	86.00 F	*86.00 FL
1		*MIRROR LH (CUT)	Not Consistent With The Impact	114.00 F	*- FL
1		*SLIDER FRAME AFTERMARKET (CUT)	Not Consistent With The Impact	171.00 F	*- FL
1		*STICKER COVER SIDE REAR LH	Not Necessary	32.00 F	*- FL
1		*WINDSHIELD	Serviceable	70.00 F	*- FL
nchise	part. L=ListIt	emDisc.	Sub Total (S\$)	1,274.00	381.00
- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	38.10
			Total Parts (S\$)	1,274.00	342.90
	1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1	1 *COVER TAIL LH 1 *COWLING FRONT LOWER 1 *COWLING SIDE FRT LH 1 *COWLING UPPER 1 *SET GUARD BALANCER GRIP 1 *SET LAMP SIGNAL FRONT 1 *MIRROR LH (CUT) 1 *SLIDER FRAME AFTERMARKET (CUT) 1 *STICKER COVER SIDE REAR LH 1 *WINDSHIELD Inchise part. L=ListltemDisc.	1 *COVER TAIL LH Not Necessary 1 *COWLING FRONT LOWER Cracked 1 *COWLING SIDE FRT LH Cut 1 *COWLING UPPER Repair 1 *SET GUARD BALANCER GRIP Cut 1 *SET LAMP SIGNAL FRONT Cut 1 *MIRROR LH (CUT) Not Consistent With The Impact 1 *SLIDER FRAME AFTERMARKET (CUT) Not Consistent With The Impact 1 *STICKER COVER SIDE REAR LH Not Necessary 1 *WINDSHIELD Serviceable **COWLING FRONT Cut Not Consistent With The Impact Not Necessary 1 *STICKER COVER SIDE REAR LH Not Necessary 1 *WINDSHIELD Serviceable **COWLING FRONT Cut **SET LAMP SIGNAL FRONT Cut **SET LAMP SIGNAL FRONT Serviceable **SLIDER FRAME AFTERMARKET (CUT) Not Consistent With The Impact **STICKER COVER SIDE REAR LH Not Necessary 1 *WINDSHIELD Serviceable **List Item Discount on L Items 0.00/10.00% (S\$)	1 *COVER TAIL LH Not Necessary 200.00 F 1 *COWLING FRONT LOWER Cracked 62.00 F 1 *COWLING SIDE FRT LH Cut 45.00 F 1 *COWLING UPPER Repair 306.00 F 1 *SET GUARD BALANCER GRIP Cut 142.00 F 1 *SET LAMP SIGNAL FRONT Cut 86.00 F 1 *MIRROR LH (CUT) Not Consistent With The Impact 114.00 F 1 *SLIDER FRAME AFTERMARKET (CUT) Not Necessary 32.00 F 1 *STICKER COVER SIDE REAR LH Not Necessary 32.00 F 1 *WINDSHIELD Serviceable 70.00 F nchise part. L=ListItlemDisc. Sub Total (\$\$) 1,274.00 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR QUOTED FOR DISMANTLE & INSTALLATION OF PARTS	New	344.00	180.00
2	SPRAY PAINT COWLING UPPER	New	80.00	80.00
	Gross Labo	ur Cost (S\$)	424.00	260.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >