



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 710E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FORK T-UNDER BRACKET (CONSISTENT)	NOT NECESSARY	850.00	-
1	STEERING CONE (CONSISTENT)	NOT NECESSARY	350.00	-
1	HANDLE BAR (CONSISTENT)	DENTED	320.00	230.00
1	HANDLE GUIDE (CONSISTENT)	BROKEN	350.00	150.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	150.00	115.00
1	BALANCER (CONSISTENT)	BROKEN	120.00	95.00
1	CRASH BAR (CONSISTENT)	SCRATCHED	750.00	400.00
1	BRAKE PEDAL (CONSISTENT)	DENTED	300.00	150.00
1	FOOTREST RIGHT (CONSISTENT)	SCRATCHED	150.00	85.00
1	EXHAUST COVER (CONSISTENT)	SCRATCHED	320.00	180.00
1	MIRROR RIGHT (CONSISTENT)	SCRATCHED	200.00	145.00
	LESS 10% DISCOUNT		-	-155.00
			3,860.00	1,395.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FORK (SN) (LOCAL REPAIR) (CONSISTENT)	BENT	1,800.00	200.00
			1,800.00	200.00
	<b><u>LABOUR</u></b>			
	LABOUR.		500.00	300.00
	FORK PRESS.		120.00	120.00
			620.00	420.00
	<b>GRAND TOTAL</b>		<b>6,280.00</b>	<b>2,015.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,600.00</b>

Report Ref No. CS/HSB23002128/Svy3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.