

Vehicle Damage Assessment Report for [SLB5512D]

Estimate Created: 14/06/2023 00:13 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 14/06/2023 16:09 by LKK_assignments (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	A-Class
Engine Type			
License Plate Number	SLB5512D	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	87,114.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,331.28 WITH 3 WORKING
DAYS

Insurlogic 4 (14/06/2023 16:07)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear bumper		1	1889.74	-10.00 %	1,700.77
Rear bumper sensor		1	217.88	-10.00 %	196.09
LH rear tail lamp		1	780.00	-10.00 %	702.00
LH rear bumper retainer		1	155.00	-10.00 %	139.50
Heat shield		1	275.00	-10.00 %	247.50
Rear bumper outer garnish LH		1	215.00	-10.00 %	193.50

Parts Subtotal 3,179.36

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
After market diffuser		1.0	966.92	0.00 %	966.92
After market exhaust (1set)		1.0	350.00	0.00 %	350.00
Rear bumper clips		10.0	5.50	0.00 %	55.00

Materials Subtotal 1,371.92

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Coating	RnR	60.00	0.00 %	60.00
Panel beating	RnR	300.00	0.00 %	300.00
Check wiring	RnR	20.00	0.00 %	20.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Rear end panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 380.00

Paint Labor Subtotal 400.00

Labor Subtotal 780.00

Summary

Repair Cost	5,331.28
Discount(0 %)	(0.00)
	5,331.28
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,331.28