

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002133/AQY3Q2**Date:** 14/07/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22003625
Claimant Vehicle No :	XE4005A	Insured Vehicle No :	GX1169G
Date of Loss:	31/01/2023	Nature of Claim:	TP
		Claim No:	CDMCG23000264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE4005A		
Make & Model:	HINO FS1ETNA, 12.9 D 28 TON 6X4 MT (M)	Engine No:	E13CAT10106
Reg. Date:	10/04/2018 (Man. Year: 2017)	Chassis No:	JHDFS1ETNXXX10012
Colour:	Red	Odometer:	164192 km
Engine Capacity:	12913 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,068.15	918.90	1,149.25	55.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	100.00	400.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,568.15	1,018.90	1,549.25	60.33
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	2,568.15	800.00	1,768.15	68.85

INSPECTION

Date of Assignment:	27/02/2023	Yap Lee Motor (HQ)
Date Inspected:	11/04/2023 Inspected At:	1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit
Estimated Period of Repair:	1.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jul 2023)	
Parts:	N/A	HINO FS1ETNA 12.9 D 28 TON 6X4 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE4005A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR -UPPER	Cut	452.00 FN	*452.00 FN
2	1		*FRONT SIDE MIRROR -LOWER	Not Necessary	398.00 FN	*- FN
3	1		*FRONT SIDE MIRROR STAY	Bent	569.00 FN	*569.00 FN
4	1		*FRONT SIDE MIRROR MOTOR	Not Necessary	758.00 FN	*- FN
					Sub Total (\$\$)	2,177.00 1,021.00
					- Nett Item Discount on N Items 5.00/10.00% (\$\$)	108.85 102.10
					Total Parts (\$\$)	2,068.15 918.90

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR CHARGES ,AND WORKMANSHIP TO DISMANTLE THE ABOVE DAMAGED PARTS WHERE CONSISTENT TO THE ACCIDENT	New	500.00	100.00
Gross Labour Cost (\$\$)			500.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >