

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23002136/RVY3M4**Date:** 22/03/2023**REFERENCE**

Insured/Claimant:	GOH WEI HAU ALWIN	Policy No:	SP2004083122-01
Date of Loss:	25/02/2023	Nature of Claim:	OD
		Claim No:	202332005717

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8878T		
Make & Model:	MERCEDES-BENZ GLB200, 1.3 PROGRESSIVE (A)	Engine No:	28291480423362
Reg. Date:	15/01/2021 (Man. Year: 2020)	Chassis No:	W1N2476872W068877
Colour:	Red	Odometer:	40401 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	S\$187,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,627.68	4,886.02	3,741.66	43.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,780.00	2,740.00	3,040.00	52.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,407.68	7,626.02	6,781.66	47.07
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	13,707.68	6,926.02	6,781.66	49.47
+ GST 8.00/8.00% (S\$)	1,096.61	554.08	542.53	49.47
Nett Amount (S\$)	14,804.29	7,480.10	7,324.19	49.47

INSPECTION

Date of Assignment:	27/02/2023	
Date Inspected:	01/03/2023 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLB200 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW8878T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	15.00 FS	*15.00 FS
2	1		*LEFT HEADLAMP UNIT	Cracked	3,361.30 FS	*3,361.30 FS
3	1		*CROSS MEMBER	Not Necessary	473.00 FS	*- FS
4	1		*FRONT SUPPORT CONNECTING CARRIER	Not Necessary	728.80 FS	*- FS
5	1		*LEFT FENDER FRONT	Not Necessary	1,479.57 FS	*- FS
6	1		*LHF EDGE GUARD	Not Necessary	9.42 FS	*- FS
7	1		*LHF FENDER MOULDING	Scratched	268.90 FS	*268.90 FS
8	1		*LHF FENDER OUTER LINEAR	Not Necessary	195.71 FS	*- FS
9	1		*LHF FENDER LOWER COVERING	Not Necessary	63.46 FS	*- FS
10	1		*BRACKET, LHF FENDER (FRONT)	Not Necessary	60.47 FS	*- FS
11	1		*FRONT BUMPER	Scratched	1,240.82 FS	*1,240.82 FS
12	1		*LHF UPP BASIC CARRIER FOR BUMPER	Not Necessary	53.72 FS	*- FS
13	1		*LHF TOP MOUNTING RAIL	Not Necessary	71.06 FS	*- FS
14	1		*LH/F BUMPER BRACKET	Not Necessary	49.07 FS	*- FS
15	1		*LHF BASIC CARRIER FOR BUMPER	Not Necessary	66.97 FS	*- FS
16	1		*IMPACT ABSORBER	Not Necessary	174.98 FS	*- FS
17	1		*LH/F FOGLAMP COVER	Not Necessary	54.47 FS	*- FS
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	260.96 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,627.68	4,886.02
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	New	380.00	380.00
2	TO REMOVE,REPLACE HEADLAMP WITH FOCUS. NETT	New	120.00	120.00
3	PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	2,880.00	1,440.00
4	RESPRAY ON LHF FENDER , FRONT BUMPER AND ACCIDENT AFFECTED AREA	New	2,400.00	800.00
Gross Labour Cost (S\$)			5,780.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >