



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 6611A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR - RH	TO REPAIR SEE LABOUR	1,557.60	-
1	FRONT DOOR GLASS OUTER MOULDING	NOT NECESSARY	105.00	-
1	FRONT DOOR INNER BOARD	NOT NECESSARY	628.50	-
1	FRONT DOOR INNER LOCK	NOT NECESSARY	217.90	-
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	192.60	-
1	FRONT DOOR REGULATOR WITH MOTOR	NOT NECESSARY	455.60	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	242.60	-
1	FRONT DOOR SIDE MIRROR	NOT NECESSARY	438.00	-
	LESS 20% DISCOUNT		-767.56	-
			3,070.24	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ROCKER PANEL SIDE SKIRT - RH (SN)	NOT NECESSARY	643.60	-
			643.60	-
	<b><u>LABOUR</u></b>			
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT DOOR - RH.		1,400.00	400.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,200.00	600.00
			2,950.00	1,000.00
<b>GRAND TOTAL</b>			<b>6,663.84</b>	<b>1,000.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,000.00</b>

Report Ref No. CS/FCI23002142/Uny3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.