

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002144/KYA3Q2**Date:** 20/06/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle No : SLF1936U **Insured Vehicle No :** YQ5746M

Date of Loss: 21/02/2023 Nature of Claim: TP Claim No: SP2004240943-01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF1936U**

Make & Model: MERCEDES-BENZ CLA180, 1.3 COUPE PROGRESSIVE (A) Engine No: 28291480367184

Reg. Date: 17/11/2020 (Man. Year: 2020) Chassis No: W1K1183842N121691

Colour: Metallic Silver Odometer: 29478 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,209.35	1,435.20	4,774.15	76.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,140.00	2,130.00	65.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,479.35	2,575.20	6,904.15	72.83
+ GST 8.00/8.00% (\$\$)	758.35	206.02	552.33	72.83
Nett Amount (\$\$)	10,237.70	2,781.22	7,456.48	72.83
+ Loss of Use (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		26.75		
Nett Liability (\$\$)		3,207.97		
Global Sum Settlement (\$\$)		3,200.00		

INSPECTION

Date of Assignment: 27/02/2023

Date Inspected: 27/02/2023 Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	MERCEDES-BENZ CLA180 1.3 COUPE PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1936U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	3,390.00 FN	*- FN
2	1		*REAR FENDER INNER SHIELD RH	Serviceable	154.00 FN	*- FN
3	8		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FN	*- FN
4	1		*REAR BUMPER	Mtg Cracked	1,456.00 FN	*1,456.00 FN
5	15		*REAR BUMPER CLIPS	Necessary	142.50 FS	*60.00 FS
6	1		*REAR BUMPER RETAINER -RH	Serviceable	103.00 FN	*- FN
7	1		*REAR BUMPER SENSOR	Serviceable	215.00 FN	*- FN
8	6		*REAR BUMPER SENSOR SEAL	Necessary	72.00 FN	*72.00 FN
9	1		*REAR SPORT RIM RH	Serviceable	853.00 FN	*- FN
10	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,525.50	1,588.00
- Nett Item Discount on N Items 5.00/10.00% (\$\$)	316.15	152.80
Total Parts (\$\$)	6,209.35	1,435.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	60.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
3	TO PANEL BEAT AND STRAIGHTEN REAR FENDER INNER PANEL REAR CHASSIS FRAME ,TO CUT AND WELD REAR RH FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,300.00	500.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,300.00	500.00
5	TO CHECK AND RECTIFY WIRING SYSTEM	New	100.00	20.00
6	TO APPLY RUST -PROOFING ON REPLACED AND REPAIRED PANELS	New	120.00	0.00
7	TO CHECK WHEEL ALIGNMENT BY COMPUTERISED	New	200.00	60.00
Gross Labour Cost (\$\$)			3,270.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >