



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 3540H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LH FENDER	TO REPAIR SEE LABOUR	680.00	-
1	REAR LH DOOR	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR LH DOOR OUTER HANDLE	NOT NECESSARY	138.60	-
1	REAR LH LAMP	CUT	380.00	380.00
	LESS 10% DISCOUNT		-244.86	-
	LESS 20% DISCOUNT		-	-76.00
			2,203.74	304.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER & FENDER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,500.00	400.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR LH FENDER AND REAR LH DOOR.		1,600.00	200.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	30.00
	ANTI RUST TREATMENT.		120.00	30.00
			3,320.00	660.00
	GRAND TOTAL		5,573.74	964.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			750.00

Report Ref No. CS/AGI23002155/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.