

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002164/UNP3Q2**Date:** 23/03/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00201712100

**Claimant Vehicle
No :** SNC7531G**Insured
Vehicle No :** SKZ9670P

Date of Loss: 16/02/2023

Nature of Claim: TP

Claim
No: SNM23D201285/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNC7531G**

Make & Model: VOLKSWAGEN GOLF, 1.4 (A)

Engine No: CXS004729

Reg. Date: 02/08/2013 (Man. Year: 2013)

Chassis No: WVWZZZAUZEW010787

Colour: White

Odometer: 187623 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,434.10	3,569.30	5,864.80	62.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	980.00	1,940.00	66.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,354.10	4,549.30	7,804.80	63.18
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	12,354.10	3,600.00	8,754.10	70.86

INSPECTION

Date of Assignment: 28/02/2023

Date Inspected: 28/02/2023 Inspected At:

2ND Auto Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre
Singapore 417808

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC7531G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,982.00 FL	*1,145.23 FL
2	2		*FRONT BUMPER SIDE RETAINERS	Bent	242.00 FL	*62.00 FL
3	1		*FRONT BUMPER LHS SIDE GRILLE	Cut	325.00 FL	*185.00 FL
4	1		*FRONT BUMPER LOWER COVER	Not fitted	350.00 FL	*- FL
5	1		*LHS FRONT FENDER	Dented / Bent	982.00 FL	*684.22 FL
6	1		*LHS FRONT FENDER INNER SHIELD (FRONT)	Not Necessary	342.00 FL	*- FL
7	1		*LHS FRONT FENDER INNER SHIELD (REAR)	Not Necessary	340.00 FL	*- FL
8	1		*LHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
9	1		*LHS FRONT SIDE VIEW MIRROR ASSY (NPA)	Repair	0.00 FL	*- FL
10	1		*LHS HEADLAMP	Scratched	1,280.00 FL	*1,045.00 FL
11	1		*LHS FRONT SHOCK ABSORBER	Not Necessary	750.00 FL	*- FL
12	1		*LHS FRONT SHOCK ABSORBER SPRING COIL	Not Necessary	280.00 FL	*- FL
13	1		*LHS FRONT LOWER ARM	Not Necessary	592.00 FL	*- FL
14	1		*LHS FRONT KNUCKLE ARM	Not Necessary	692.00 FL	*- FL
15	1		*LHS FRONT WHEEL BEARING	Not Necessary	492.00 FL	*- FL
16	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
17	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*LHS FRONT FENDER LOWER BLACK STICKER	Necessary	60.00 FS	*30.00 FS
19	1		*LHS FRONT DOOR LOWER BLACK STICKER	Necessary	150.00 FS	*100.00 FS
20	1		*LHS FRONT SPORTS RIM	Cut	1,280.00 FS	*600.00 FS
					Sub Total (\$\$)	10,299.00 3,881.45
					- List Item Discount on L Items 10.00/10.00% (\$\$)	864.90 312.15
					Total Parts (\$\$)	9,434.10 3,569.30
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	300.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED AREAS	New	1,000.00	600.00
3	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION	New	350.00	0.00
4	TO REMOVE AND REPLACE LHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM)	New	300.00	0.00
5	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	60.00
6	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION -FOCUS HEADLAMP	New	150.00	20.00
Gross Labour Cost (S\$)			2,920.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >