

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002168/KNP3Q2**Date:** 23/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00181802201

**Claimant Vehicle
No :** SKL8701P**Insured
Vehicle No :** SJS3689A

Date of Loss: 27/02/2023

Nature of Claim: TP

Claim
No: SNM23D201504/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKL8701P**

Make & Model: HONDA VEZEL HYBRID, 1.5 x (A)

Engine No: LEB5957790

Reg. Date: 15/11/2017 (Man. Year: 2017)

Chassis No: RU31257773

Colour: Metallic Red

Odometer: 69455 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Toyo 5 mm

Rear Left Side: Toyo 4 mm

Front Right Side: Toyo 5 mm

Rear Right Side: Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,828.18	2,102.78	3,725.40	63.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,610.00	1,690.00	51.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,128.18	3,712.78	5,415.40	59.33
+ GST 8.00/8.00% (S\$)	730.25	297.02	433.23	59.33
Nett Amount (S\$)	9,858.43	4,009.80	5,848.63	59.33

INSPECTION

Date of Assignment: 28/02/2023

Date Inspected: 28/02/2023 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL8701P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	1,050.40 FL	*1,050.40 FL
2	1		*REAR TAIL GATE ABSORBER	Serviceable	360.00 FL	*- FL
3	1		*REAR TAIL GATE LOGO	Not Necessary	20.70 FL	*- FL
4	1		*REAR TAIL GATE LOGO VEZEL	Not Necessary	53.40 FL	*- FL
5	1		*REAR TAIL GATE LOGO HYBRID	Necessary	70.20 FL	*70.20 FL
6	1		*REAR TAIL GATE LOCK	Dented	92.20 FL	*92.20 FL
7	1		*REAR TAIL GATE INNER TRIM BOARD	Serviceable	185.20 FL	*- FL
8	1		*REAR TAIL GATE WEATHERSHIELD	Serviceable	105.20 FL	*- FL
9	2		*REAR TAIL GATE LAMP LH & RH	Serviceable	849.40 FL	*- FL
10	1		*REAR LAMP RH	Serviceable	486.70 FL	*- FL
11	1		*REAR LAMP LOWER BRACKET RH	Serviceable	55.00 FL	*- FL
12	1		*REAR LAMP LH	Serviceable	486.70 FL	*- FL
13	1		*REAR LAMP LOWER BRACKET LH	Serviceable	55.00 FL	*- FL
14	1		*REAR BUMPER	Buckled	532.40 FL	*532.40 FL
15	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	17.50 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	17.50 FL	*- FL
17	1		*REAR BUMPER REFLECTOR RH	Serviceable	89.40 FL	*- FL
18	1		*REAR BUMPER REFLECTOR LH	Serviceable	89.40 FL	*- FL
19	1		*REAR END PANEL	Repair	538.40 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	98.20 FL	*- FL
21	1		*REAR SPARE TYRE TRIM BOARD	Serviceable	459.20 FL	*- FL
22	1		*REAR UNDER COVER	Serviceable	190.40 FL	*- FL
23	1		*SET REAR UNDER COVER CLIPS /SCREW	Necessary	25.00 FL	*25.00 FL
24	1		*INNER BUZZER	Serviceable	80.10 FL	*- FL
25	1		*OUTER BUZZER	Cracked	80.10 FL	*80.10 FL
26	1		*SET REAR TAILGATE GLASS MOULDING	Necessary	115.68 FL	*115.68 FL
27	1		*KEY LOCK SENSOR	Serviceable	88.10 FL	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
29	2		*SET REAR BUMPER SHIELD CLIPS	Not Necessary	45.00 FS	*- FS
30	1		*SET SOUND PROOF	Necessary	300.00 FS	*200.00 FS
31	1		*SET REVERSE SENSOR	Dented	320.00 FS	*200.00 FS
32	1		*SET REAR TAILGATE TRIM BOARD CLIPS	Necessary	35.00 FS	*35.00 FS
33	1		*SET REAR END PANEL GARNISH CLIP	Necessary	50.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,086.48	2,495.98
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,258.30	393.20
Total Parts (\$\$)					5,828.18	2,102.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,200.00	600.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGE PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	600.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	60.00
5	TO REMOVE /REPLACE /REFIX TAIL GATE COMPARTMENT ,MECHANISM TO NEW TAILGATE	New	150.00	60.00
6	TO REMOVE /REFIX /REPLACE REAR WINDSCREEN TO NEW TAILGATE	New	150.00	120.00
7	TO REMOVE /REFIX REAR INNER COMPARTMENT TO FACILITATES REPAIR	New	180.00	60.00
8	TO REMOVE /REFIX REVERSE CAMERA	New	100.00	40.00
9	TO REMOVE /REPLACE /REFIX REAR REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			3,300.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >