

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23002169/UWY3M4**Date:** 17/04/2023**REFERENCE**

Insured/Claimant:	LOH WAI CHAN	Policy No:	DMPG22017170	
Date of Loss:	10/02/2023	Nature of Claim:	OD	Claim No: CDMPG23000382

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8833G		
Make & Model:	BMW X3, 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A)	Engine No:	F152K428B48B20A
Reg. Date:	29/12/2020 (Man. Year: 2020)	Chassis No:	WBATS720409E42384
Colour:	Silver	Odometer:	20235 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,287.79	10,296.00	12,991.79	55.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	860.00	2,410.00	73.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,557.79	11,156.00	15,401.79	57.99
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	26,557.79	10,456.00	16,101.79	60.63
+ GST 8.00/8.00% (S\$)	2,124.63	836.48	1,288.15	60.63
Nett Amount (S\$)	28,682.42	11,292.48	17,389.94	60.63

INSPECTION

Date of Assignment:	28/02/2023	Present Location:	TLM Automobile Pte Ltd (HQ)
Date Inspected:	09/03/2023	Inspected At:	TLM Automobile Pte Ltd (HQ) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	M1-SUV	BMW X3 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8833G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper (WCP)	Deformed/Torn	1,798.00 FL	*1,440.00 F
2	2		*Front bumper side retainer (WCP)	Not Necessary	190.00 FL	*- F
3	1		*Front bumper lower (WCP)	Grazed	892.00 FL	*750.00 F
4	1		*Front bumper towing cap (WCP)	Not Necessary	75.00 FL	*- F
5	2		*Front bumper sensor (WCP)	Not Necessary	596.00 FL	*- F
6	2		*Front bumper sensor seal (WCP)	No such part	70.00 FL	*- F
7	2		*Front bumper grille (WCP)	Not Necessary	440.00 FL	*- F
8	1		*Front bumper grille inner bracket (WCP)	Not Necessary	95.00 FL	*- F
9	1		*Front bumper top rubber (WCP)	Not Necessary	112.00 FL	*- F
10	1		*Front bumper sponge (WCP)	Torn	115.00 FL	*90.00 F
11	1		*Front bumper reinforcement (WCP)	Repair	950.00 FL	*- F
12	1		*Front bumper reinforcement cross (WCP)	Not Necessary	550.00 FL	*- F
13	1		*Headlamp 2PIECES (WCP)	N/s Cracked/ O/s Not Necessary	9,360.00 FL	*4,250.00 F
14	2		*Headlamp lower bracket (WCP)	Not Necessary	500.00 FL	*- F
15	2		*Headlamp ballast (WCP)	Not Necessary	2,010.00 FL	*- F
16	1		*Front support panel (FIT) (WCP)	Repair	278.00 FL	*- F
17	1		*Front support panel (REAR SECTION) (WCP)	Not Necessary	295.00 FL	*- F
18	1		*Aircon condenser (WCP)	Not Necessary	1,250.00 FL	*- F
19	1		*Bonnet (WCP)	Buckled	2,150.00 FL	*2,020.00 F
20	1		*Bonnet emblem (WCP)	Necessary	110.00 FL	*80.00 F
21	1		*Front coolant assy (WCP)	Not Necessary	1,350.00 FL	*- F
22	1		*Front bumper clips SET (WCP)	Necessary	35.00 FS	*15.00 F
23	10		*Front bumper lower clips	Not Necessary	35.00 FS	*- FS
24	5		*Front bumper grille clips	Not Necessary	12.50 FS	*- FS
25	10		*Bonnet insulator clips	Not Necessary	25.00 FS	*- FS
Supplementary #1						
26	2		*2PCS FRONT GRILLE (WCP)	Cracked	811.56 FL	*360.00 F
27	1		*1PC FRONT GRILLE INNER BRACKET (WCP)	Cracked	270.25 FL	*245.00 F
28	1		*1PC AIR GUIDE RADIATOR TOP (WCP)	Torn	132.50 FL	*110.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (\$)						24,507.81
						9,360.00
- List Item Discount on L Items 5.00/0.00% (\$)						1,220.02
						0.00
+ Margin on L,N Items 0.00/10.00% (\$)						0.00
						936.00
Total Parts (\$)						23,287.79
						10,296.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check electrical lighting concerned.	New	120.00	20.00
2	To replace and remove front bumper sensor.	New	150.00	40.00
3	To conduct diagnostic check.	New	200.00	0.00
4	To replace, remove aircon condenser and refill aircon gas.	New	200.00	0.00
5	To replace and remove front coolant assy and refill coolant.	New	100.00	0.00
6	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	1,200.00	400.00
7	Putty and spray painting of the affected portion.	New	1,300.00	400.00
Gross Labour Cost (S\$)			3,270.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >