

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002171/KWP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00095662201

Claimant Vehicle No : SLL1973E **Insured Vehicle No :** GBE746G

Date of Loss: 27/02/2023 Nature of Claim: TP Claim No: SNM23D201499/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL1973E**

Make & Model: TOYOTA CAMRY, 2.5 G HYBRID CVT (A) Engine No: A25A0109175

Reg. Date: 27/02/2019 (Man. Year: 2018) Chassis No: AXVH701021502

Colour: Metallic Black Odometer: 193336 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,747.69	8,928.07	4,819.62	35.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	2,480.00	750.00	23.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,977.69	11,408.07	5,569.62	32.81
Approved Total (Overridden) (\$\$)		9,100.00		
Nett Amount (\$\$)	16,977.69	9,100.00	7,877.69	46.40

INSPECTION

Date of Assignment: 28/02/2023

Date Inspected: 28/02/2023 Inspected At: Em Solution Pte Ltd (160 Sin Ming) (HQ)
160 Sin Ming Drive, #03-19 Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	TOYOTA CAMRY 2.5 G HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1973E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,373.90 FL	*1,143.70 FL
2	1		*REAR BOOT LID TOYOTA LOGO	Necessary	86.00 FL	*86.00 FL
3	1		*REAR BOOT LID GARNISH	Warped	204.50 FL	*204.50 FL
4	1		*REAR BOOT LID GARNISH CAMRY EMBLEM	Necessary	65.60 FL	*65.60 FL
5	1		*REAR BOOT LID SWITCH	Serviceable	200.70 FL	*- FL
6	1		*REAR BOOT LID REVERSE CAMERA GARNISH	Dented	195.60 FL	*195.60 FL
7	2		*REAR BOOT LID LICENSE PLATE LAMP L/R	Serviceable	347.00 FL	*- FL
8	1		*REAR BOOT LID HYBRID SYNERGY DRIVE BADGE	Necessary	58.90 FL	*58.90 FL
9	2		*REAR BOOT LID HINGE L/R	Repair	431.60 FL	*- FL
10	1		*REAR BOOT LID REFLECTOR LAMP L/R	O/S Cut	1,472.80 FL	*585.20 FL
11	1		*REAR BOOT LID INNER UPHOLSTERY TRIM BOARD	Serviceable	604.50 FL	*- FL
12	1		*REAR BOOT LID MECHANISM LOCK	Dented	480.20 FL	*339.80 FL
13	2		*REAR LAMP L/R	N/S Cut / O/S Cracked	2,143.20 FL	*1,770.20 FL
14	1		*REAR LAMP PANEL RH	Bent	385.20 FL	*385.20 FL
15	1		*REAR LAMP LOWER BRACKET L/R	O/S Cracked	351.20 FL	*175.60 FL
16	2		*REAR LAMP CLIPS	Necessary	15.40 FL	*15.40 FL
17	1		*REAR FENDER RH	Buckled	1,280.40 FL	*1,065.30 FL
18	2		*REAR FENDER TOP GARNISH L/R	Dented / Cut	435.60 FL	*435.60 FL
19	1		*REAR FENDER INNER UPHOLSTERY TRIM RH	Deformed	618.30 FL	*566.10 FL
20	1		*REAR WINDSCREEN MOULDING	Necessary	192.90 FL	*192.90 FL
21	1		*REAR BUMPER	Bent	855.90 FL	*729.90 FL
22	1		*REAR BUMPER SIDE RETAINER L/R	O/S Distorted	267.60 FL	*133.80 FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	377.80 FL	*377.80 FL
24	2		*REAR BUMPER BRACKET L/R (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*REAR BUMPER LOWER GARNISH	Dented / Distorted	422.90 FL	*422.90 FL
26	2		*REAR BUMPER REFLECTOR L/R	Serviceable	179.40 FL	*- FL
27	1		*REAR BUMPER UNDERSHIELD	Serviceable	441.75 FL	*- FL
28	1		*REAR END PANEL	Bent	785.20 FL	*581.20 FL
29	1		*REAR END PANEL TOP GARNISH	Dented	356.20 FL	*296.20 FL
30	1		*REAR LOCK CATCH HOOK	Repair	133.75 FL	*- FL
31	1		*REAR LOCK CATCH HOOK COVER	Dented	70.70 FL	*70.70 FL
32	1		*REAR BOOT WEATHERSTRIP	Cut	311.60 FL	*254.60 FL
33	1		*REAR END PANEL LOCK SENSOR	Serviceable	189.70 FL	*- FL
34	1		*REAR END PANEL LOCK SENSOR WIRE (NPA)	Not Necessary	0.00 FL	*- FL
35	1		*REAR SPARE TIRE PANEL	Repair	785.20 FL	*- FL
36	1		*REAR PANEL TOOLS FOAM TRAY	Deformed	551.60 FL	*360.60 FL
37	1		*REAR SPARE TIRE PANEL COVER	Deformed	433.79 FL	*433.79 FL
38	2		*REAR LAMP GARNISH L/R	Cut	197.00 FL	*197.00 FL
39	1		*REVERSE CAMERA	Shorted	250.00 FS	*250.00 FS
40	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
41	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
42	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	35.00 FS	*35.00 FS
43	1		*SET REAR FENDER INNER UPHOLSTERY CLIPS	Not Necessary	45.00 FS	*- FS
44	1		*SET REAR BOOT LID TRIM BOARD CLIPS	Not Necessary	45.00 FS	*- FS
45	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
46	1		*SET REAR LICENSE PLATE	Serviceable	50.00 FS	*- FS

Report was unsubmitted during this print-out.

5/15/23, 11:47 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	18,073.59
					- List Item Discount on L Items 25.00/25.00% (S\$)	4,325.90
					Total Parts (S\$)	13,747.69
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRING CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE & REPLACE UPHOLSTERY CUSHION SEAT & TRIM GARNISHES	New	150.00	100.00
3	TO REMOVE ,REINSTAL REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE ,TRANSFER BOOT LID COMPONENTS	New	100.00	60.00
5	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	1,100.00
6	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,200.00	900.00
7	TO REMOVE & RENEW REVERSE SENSOR	New	100.00	50.00
8	TO REMOVE,REPLACE REVERSE CAMERA	New	100.00	40.00
9	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	90.00
Gross Labour Cost (\$\$)			3,230.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >