

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002173/SVP3Q2**Date:** 19/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00014782203

Claimant Vehicle No : SJN8779S **Insured Vehicle No :** PC9041S

Date of Loss: 16/02/2023 Nature of Claim: TP Claim No: SNM23D201317/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN8779S**

Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: MR20484359W

Reg. Date: 12/09/2017 (Man. Year: 2017) Chassis No: SJNFBAJ11U2012182

Colour: Grey Odometer: 126458 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R19 Rear Tyre Size: 225/45 R19

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,160.50	4,606.16	9,554.34	67.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,290.00	3,000.00	69.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,450.50	5,896.16	12,554.34	68.04
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	18,450.50	4,700.00	13,750.50	74.53
+ GST 8.00/8.00% (S\$)	1,476.04	376.00	1,100.04	74.53
Nett Amount (S\$)	19,926.54	5,076.00	14,850.54	74.53

INSPECTION

Date of Assignment: 28/02/2023

Date Inspected: 01/03/2023 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN8779S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	3,062.50 FL	*2,936.00 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	150.50 FL	*150.50 FL
3	1		*TAILGATE OUTER GARNISH	Not Necessary	337.90 FL	*- FL
4	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	70.00 FL	*- FL
5	1		*TAILGATE CENTRE EMBLEM	Not Necessary	79.90 FL	*- FL
6	1		*TAILGATE QASHQAI EMBLEM	Necessary	87.00 FL	*87.00 FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	357.80 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
9	1		*TAILGATE LOCK	Not Necessary	173.30 FL	*- FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	45.50 FL	*- FL
11	1		*TAILGATE RH LAMP	Not Necessary	367.40 FL	*- FL
12	1		*TAILGATE RH LAMP GASKET	Not Necessary	22.00 FL	*- FL
13	1		*TAILGATE LH LAMP	Not Necessary	367.40 FL	*- FL
14	1		*TAILGATE LH LAMP GASKET	Not Necessary	22.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Not Necessary	188.20 FL	*- FL
16	1		*TAILGATE WIPER MOTOR	Not Necessary	655.20 FL	*- FL
17	1		*REAR BUMPER	Broken	765.40 FL	*765.40 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
19	1		*REAR BUMPER RH REFLECTOR	Not Necessary	65.70 FL	*- FL
20	1		*REAR BUMPER LH REFLECTOR	Not Necessary	65.70 FL	*- FL
21	1		*REAR BUMPER TOWING COVER	Not Necessary	28.00 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Not Necessary	621.80 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Not Necessary	166.20 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Not Necessary	166.20 FL	*- FL
25	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	47.80 FL	*- FL
26	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	47.80 FL	*- FL
27	1		*REAR BUMPER INNER SPONGE	Broken	142.00 FL	*142.00 FL
28	1		*RH TAILLAMP ASSY	Not Necessary	415.60 FL	*- FL
29	1		*RH TAILLAMP GASKET	Not Necessary	24.00 FL	*- FL
30	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	18.00 FL	*- FL
31	1		*RH TAILLAMP PANEL	Not Necessary	133.20 FL	*- FL
32	1		*LH TAILLAMP ASSY	Not Necessary	415.60 FL	*- FL
33	1		*LH TAILLAMP GASKET	Not Necessary	24.00 FL	*- FL
34	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	18.00 FL	*- FL
35	1		*LH TAILLAMP PANEL	Not Necessary	133.20 FL	*- FL
36	1		*END PANEL	Buckled	553.20 FL	*553.20 FL
37	1		*END PANEL INNER GARNISH	Cracked	83.30 FL	*83.30 FL
38	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	70.00 FL	*15.00 FL
39	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	404.70 FL	*- FL
40	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
41	1		*REAR RH FENDER SPLASH SHIELD	Not Necessary	118.90 FL	*- FL
42	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FL	*- FL
43	1		*REAR LH FENDER INNER TRIM BOARD	Not Necessary	404.70 FL	*- FL
44	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
45	1		*REAR LH FENDER SPLASH SHIELD	Not Necessary	118.90 FL	*- FL
46	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FLOOR PANEL TOP COVER BOARD	Not Necessary	456.20 FL	*- FL
48	1		*REAR FLOOR PANEL SIDE TRAY GARNISH RH	Not Necessary	247.10 FL	*- FL
49	1		*REAR FLOOR PANEL SIDE TRAY GARNISH LH	Not Necessary	247.10 FL	*- FL
50	1		*REAR FLOOR PANEL SPONGE TRAY LH	Not Necessary	99.10 FL	*- FL
51	1		*REAR FLOOR PANEL SPONGE TRAY RH	Not Necessary	99.10 FL	*- FL
52	1		*EXHAUST SILENCER HEAT SHIELD	Not Necessary	178.00 FL	*- FL
53	1		*EXHAUST SILENCER	Not Necessary	783.90 FL	*- FL
54	1		*EXHAUST SILENCER GASKET	Not Necessary	56.00 FL	*- FL
55	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
56	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*40.00 FS
57	1		*TAILGATE CHROME MOULDING	Not Necessary	450.00 FS	*- FS
58	1		*TAILGATE REVERSE CAMERA	Not Necessary	750.00 FS	*- FS
59	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
60	1		*REAR BUMPER REVERSE SENSOR	Malfunction	380.00 FS	*200.00 FS
61	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					15,525.00	5,082.40
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,364.50	476.24
Total Parts (\$\$)					14,160.50	4,606.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANEL AND AREAS	New	1,600.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	30.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	80.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	30.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	180.00	30.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS (4 SENSORS)	New	150.00	30.00
9	REMOVE AND REPLACE REAR INNER BOARD ,GARNISH AND TRIMS TO ASSIST REPAIR	New	280.00	60.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	0.00
Gross Labour Cost (\$\$)			4,290.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >