3/15/23, 10:27 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI23002174/WQP3M4

15/03/2023 Date:

**REFERENCE** 

No:

Price:

China Taiping Insurance (Singapore) Handling Insurer: Pte. Ltd.

Policy No: DMCVSNW00136452202

YQ1591T

**Claimant Vehicle** 

**Insured Vehicle** 

SNH3501T No:

Claim Date of Loss: 20/02/2023 Nature of Claim: TP SNM23D201395/C02 No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SNH3501T

TOYOTA ALPHARD, 2.5 HYBRID ELEGANCE Make & Model:

Engine No: 2AR2830079 (A)

JTNHS3DH008081352 Reg. Date: 20/10/2022 (Man. Year: 2022) Chassis No: Colour: Black Odometer: 14350 km

**Engine Capacity:** 2494 cc

Market Value/New Car

N/A

Market Value/New Car Price Sum Insured (S\$):

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17 Rear Left Side: Front Left Side: Yokohama 7 mm Yokohama 7 mm Rear Right Side: Yokohama 7 mm Front Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

28/02/2023 Date of Assignment:

LIAN HUP SENG MOTOR WORKS

BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 Date Inspected: 01/03/2023 Inspected At:

#01-345

SINGAPORE 569538

Estimated Period of Repair: 8.0 days

SHIAU CHAN Adjuster: Mohdakid Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/15/23, 10:27 AM Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$16,000.00 - \$18,000.00

3/15/23, 10:27 AM Adjuster Report

### REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: M1-MPV TOYOTA ALPHARD 2.5 HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNH3501T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

3/15/23, 10:27 AM Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >