

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002178/AVP3Q2**Date:** 25/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00105742202

**Claimant Vehicle No :** PC7868L **Insured Vehicle No :** SMF7357P

Date of Loss: 22/02/2023 Nature of Claim: TP Claim No: SNM23D201449/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PC7868L**

Make & Model: HIGER KLQ6128K, 9.5 D (M) Engine No: WP10H375E623618J047555

Reg. Date: 14/02/2019 (Man. Year: 2018) Chassis No: LKLR1LSL3JA738017

Colour: White Odometer: 223941 km

Engine Capacity: 9511 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,750.00	3,200.00	2,550.00	44.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,440.00	1,160.00	44.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,350.00</b>	<b>4,640.00</b>	<b>3,710.00</b>	<b>44.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,350.00</b>	<b>3,700.00</b>	<b>4,650.00</b>	<b>55.69</b>

**INSPECTION**

Date of Assignment: 28/02/2023

Date Inspected: 02/03/2023 Inspected At: YSK Auto Workshop (HQ)  
1 Kaki Bukit Avenue 6 @ AutoBay, #01-71  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Apr 2023)	
Parts:	N/A	HIGER KLQ6128K 9.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7868L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LUGGAGE COMPARTMENT COVER	Buckled	2,500.00 FS	*1,300.00 FS
2	1		*LUGGAGE COMPARTMENT COVER HANDLE	Not Necessary	150.00 FS	*- FS
3	1		*LUGGAGE COMPARTMENT COVER HANDLE REFLECTOR	Not Necessary	100.00 FS	*- FS
4	1		*UTILITY COMPARTMENT COVER	Buckled	1,200.00 FS	*900.00 FS
5	1		*REAR WHEEL PANEL	Buckled	1,500.00 FS	*1,000.00 FS
6	1		*REAR WHEEL RIM COVER	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,750.00	3,200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,200.00	600.00
2	SPRAY PAINTING TO AFFECTED AREAS	New	1,200.00	800.00
3	TO APPLY TUFF COAT	New	200.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>2,600.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >