

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO23002180/Avy3m4
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 O TOWERSINGAPORE 048623		Date:	08/03/2023
				Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKX 9652C	Veh. Inspected	ł	SMJ 618L
	Policy No.	D23MTPV01000148	Coverage (\$)		0.00
	Claim No.	CMTD2300789/SYH	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		28/02/2023
2.	Vehicle Particulars & Condition				
	Make & Model	BMW 316	c.c		1598
	Engine No.	HIDDEN	Year of Reg.		2014
	Chassis No.	WBA3A16060NS36093	Colour		BLACK
	Odometer	135483 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/45 R18	GITI		6 mm
	L/H Front Tyre	225/45 R18	GITI		6 mm
	R/H Rear Tyre	225/45 R18	GITI		6 mm
	L/H Rear Tyre	225/45 R18	GITI		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
5.	General Information				
	Accident Date	22/02/2023	Inspect Date /	Time	01/03/2023 ( 01:53 PM )
	Survey held at	QMO ENGINEERING			
	10 KAKI BUKIT ROAD 2, #03-18, FIRST EAST CENTRE, SINGAPORE 417868				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMO23002180/Avy3m4

Inspected By

ADRIAN LING WAI PING

Licensed Appraiser

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser