

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG23002194/AWP3E2**Date:** 07/07/2023REFERENCEInsured/Claimant: PALLVI D/O NARENDRALAL NANALAL MEHTA MRS
PALLVI

Policy No: 1900156323-01

Date of Loss: 24/02/2023

Nature of Claim: OD Claim No: 5545108269SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMN8824J**

Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)

Engine No: DAX056963

Reg. Date: 30/08/2019 (Man. Year: 2019)

Chassis No: WAUZZZF5K2108343

Colour: White

Odometer: 56377 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$168,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,251.00	7,449.20	16,801.80	69.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,272.00	2,422.00	2,850.00	54.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,523.00	9,871.20	19,651.80	66.56
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	28,523.00	8,871.20	19,651.80	68.90
+ GST 8.00/8.00% (S\$)	2,281.84	709.70	1,572.14	68.90
Nett Amount (S\$)	30,804.84	9,580.90	21,223.94	68.90

INSPECTION

Date of Assignment: 01/03/2023

Date Inspected: 28/02/2023 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,536.00 FS	*1,228.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	357.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - RH	Not Necessary	45.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	133.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	170.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Repair	900.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Cut	614.00 FS	*491.20 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	260.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cut	4,155.00 FS	*3,324.00 FS
10	1		*QUATTRO INSCRIPTION	Necessary	118.00 FS	*94.00 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	288.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	691.00 FS	*552.80 FS
13	1		*FRONT BUMPER OUTER GRILLE BAFFLE - RH	Missing	109.00 FS	*86.80 FS
14	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	46.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	210.00 FS	*168.00 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,104.00 FS	*- FS
17	1		*FRONT BUMPER TOP COVER	Not Necessary	152.00 FS	*- FS
18	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
19	1		*AIR CONDITIONER STICKER	Not Necessary	24.00 FS	*- FS
20	1		*HORN HIGH TONE - RH	Not Necessary	220.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Not Necessary	457.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - RH	Cracked	140.00 FS	*111.60 FS
25	1		*HEADLIGHT - RH	Not Necessary	9,226.00 FS	*- FS
26	1		*LIFT CYLINDER - RH	Damaged	162.00 FS	*129.60 FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	150.00 FS	*- FS
28	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	20.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE - RH	Not Necessary	70.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - CENTER	Not Necessary	61.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	61.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	326.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER	Not Necessary	182.00 FS	*- FS
34	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,504.00 FS	*1,202.40 FS
35	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
36	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **24,251.00** **7,449.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	1,250.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,272.00	2,422.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >