

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 2103J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)	DISTORTED	865.00	731.00
1	REAR BUMPER LOWER LIP (N)	DEFORMED / TORN	480.00	480.00
1	REAR BUMPER RETAINER LH (N)	NOT NECESSARY	81.00	-
1	REAR BUMPER RETAINER RH (N)	BENT	81.00	81.00
1	BOOTLID (N)	DENTED / BUCKLED	782.00	782.00
1	BOOTLID LOGO (N)	NECESSARY	63.00	52.00
1	BOOTLID LOCK (N)	BENT / TWISTED	258.00	197.00
1	BOOTLID LOCK STRIKER (N)	NOT NECESSARY	50.00	-
2	BOOTLID HINGE (N)	NOT NECESSARY	256.00	-
1	BOOTLID WEATHERSTRIP (N)	TWISTED	260.00	168.00
1	BOOTLID LICENCE PLATE GARNISH (N)	CRACKED	375.00	245.00
1	TAILLAMP LH (N)	SCRATCHED / CRACKED	574.00	468.00
1	TAILLAMP RH (N)	CRACKED	574.00	468.00
1	REAR END PANEL (N)	BADLY DENTED	689.00	442.00
1	REAR END PANEL TOP GARNISH (N)	TWISTED	275.00	166.00
1	SPARE TYRE PANEL (N)	TO REPAIR SEE LABOUR	589.00	-
1	SPARE TYRE PANEL TOP BOARD (N)	TORN	345.00	268.00
1	REAR FENDER RH (N)	TO REPAIR SEE LABOUR	1,213.00	-
1	REAR FENDER INNER SHIELD RH (N)	NOT NECESSARY	225.00	-
1	REAR FENDER INNER TRIM RH (N)	TORN	475.00	316.00
1	REAR FENDER INNER TRIM LH (N)	NOT NECESSARY	475.00	-
1	EXHAUST MOUNTING (N)	NOT NECESSARY	80.00	-
1	EXHAUST MOUNTING SILENCER (N)	TO REPAIR SEE LABOUR	790.30	-
	LESS 10% DISCOUNT		-985.53	-486.40
			8,869.77	4,377.60
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/SMO23002196/Uwy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR FENDER INNER SHIELD CLIP LH (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER INNER SHIELD CIP RH (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	90.00	-
1	SET BOOTLID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	480.00	200.00
1	JOINT SEALANT END PAEL (SN)	NECESSARY	100.00	50.00
			970.00	280.00
	<u>LABOUR</u>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		100.00	20.00
	REMOVE AND RENEW REAR SENSOR.		120.00	50.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		150.00	80.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL, REAR FENDER RH AND EXHAUST MOUNTING SILENCER.		1,500.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	900.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	60.00
			3,470.00	1,910.00
	GRAND TOTAL		13,309.77	6,567.60

RECOMMENDED COST OF LUMP SUM REPAIRS		5,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO23002196/Uwy3e2

CHUA KANG SENG

Licensed Appraiser