



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7639K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR (N/S)	TO REPAIR SEE LABOUR	2,263.90	-
1	SIDE PANEL (N/S)	TO REPAIR SEE LABOUR	322.50	-
1	HEAD LAMP (N/S)	SCRATCHED/ CRACKED	896.90	896.90
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	87.30	-
	LESS 10% DISCOUNT		-357.06	-
	LESS 25% DISCOUNT		-	-224.22
			3,213.54	672.68
<u>SPECIAL NETT ITEMS</u>				
1	DOOR STICKER ('ROC') (SN)	NECESSARY	50.00	30.00
1	DOOR ADVERTISEMENT (STICKER N/S) (SN)	NECESSARY	380.00	250.00
			430.00	280.00
<u>LABOUR</u>				
	TO REMOVE, REPAIR DOOR, SIDE PANEL. INCLUSIVE OF THE REPAIR OF FRONT DOOR (N/S) AND SIDE PANEL (N/S).		680.00	350.00
	TO SPRAY PAINTING.		680.00	450.00
			1,360.00	800.00
GRAND TOTAL			5,003.54	1,752.68

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00
---	--	--	-----------------

Report Ref No. CS/SMO23002200/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.