

RECEIVED


REF:

INC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 ID / TP / NS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 Workshop No: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Rel. or Market Value: \_\_\_\_\_  
 IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Sect: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 C.A. / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT  
 WP  
 Lim TS



Veh No: SH 9180L Yr Regn: 2016 June  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai 140 C.D. 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KM HLB414MG4090127  
 Gen. Cond: Good Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brakes: In order / Jammed / Leaked / Burnt or  
 Mod: W/S / S/Rim / STD / R/Rim or  
 Tyre Size: F: 205/60R16  
 R: \_\_\_\_\_  
 ES / DUN / EXNOVA / GY / PS / LIZA / MIC / DHTSU / PIR / SWM /  
 TOYO / YDKID or Weslake  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 28/2/23  
 Survey held at Comfort Lodge  
 Des. of Damage: Frnt / Rear / O/S / N/S / U/C / Bottom or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time, File Return to?  
 Paper/Printer:  
 Date of Issue / Date of

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee: \_\_\_\_\_



PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Lim Tien Siong			
	Front No. Plate With Trim Cover		SH 9180L	P2/2 hit - \$55.00
				\$55.00
				\$5.50
				\$49.50
	Front Fender Adv. Sticker RH / LH	2	\$100.00	\$200.00
	<b>SPARE PARTS TOTAL</b>			\$13,707.66
	<b>Labour Charge</b>			
	Panel Beating			\$1,200.00
	Spray Painting Charge			\$1,200.00
	Wiring Charge			\$50.00
	Tuff Kote			\$50.00
	Towing Charge			NIL
	Remove/Refix Reverse Sensor			\$120.00
	Remove/Refix Radiator			\$90.00
	Remove/Refix Aircon & Refill Gas			\$150.00
	<b>TOTAL LABOUR</b>			\$ 2,860.00
	<b>(FRONT) ESTIMATE TOTAL</b>			\$ 16,627.66
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LH X  
RH X  
560  
BDS  
750  
30  
30  
X  
X  
?  
?100

Tan Li 97495749  
'wp' 28/2/22 @ 330pm  
1/5 Resurvey after repair  
3 days

- To provide Japi book value  
- To check repair limit.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# COMFORTDELGRO ENGINEERING PTE LTD

P1/2

## REPAIR ESTIMATE

DATE: 28.02.2023

3P INSURANCE: INCOME

MODEL: HYUNDAI I40 (FRONT) & (REAR)

VEH NO.: SH 9180L

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid	1		\$2,609.80 <i>bt</i>
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60 <i>?</i>
	Bootlid Lock Upper	1		\$114.90 <i>?</i>
	Bootlid Lock Lower	1		\$31.70 <i>x</i>
	Bootlid Hyundai Plate	1		\$21.10 <i>ner</i>
	Bootlid 'H' Emblem	1		\$63.10 <i>ner</i>
	Bootlid CRDI Plate	1		\$52.40 <i>ner</i>
	Bootlid I40 Emblem	1		\$67.90 <i>ner</i>
	Bootlid Lamp (LH/RH)	2	\$622.20	\$1,244.40 <i>x</i>
	Bootlid Moulding	1		\$85.00 <i>?</i>
	Bootlid Lower Outer Garnish	1		\$227.90 <i>x</i>
	Rear Bumper	1		\$553.00 <i>de</i>
	Rear Bumper Reinforcement	1		\$428.40 <i>ner</i>
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 <i>ner</i>
	Rear Bumper Side Bracket RH/LH	2	\$80.30	\$160.60 <i>dis</i>
	Rear Bumper Sponge	1		\$119.50 <i>ner</i>
	Rear Bumper Under Cover	1		\$228.00 <i>?</i>
	Rear Bumper Reflector RH / LH	2	\$32.00	\$64.00 <i>RMals</i>
	Tail Lamp (LH/RH)	2	\$697.80	\$1,395.60 <i>?</i>
	Tail Lamp Quarter Panel (RH/LH)	2	\$453.00	\$906.00 <i>x</i>
	Exhaust Muffler RH/LH	2	\$967.70	\$1,935.40 <i>?</i>
	Exhaust Pipe Hanger	2	\$58.55	\$117.10 <i>?</i>
	Exhaust Pipe Centre	1		\$730.10 <i>x</i>
	Rear End Panel	1		\$526.70 <i>bt</i>
	Rear End Lower Panel	1		\$495.50 <i>?</i>
	Rear End Panel Garnish	1		\$57.70 <i>?</i>
	Rear Fender LH	1		\$2,171.40 <i>x</i>
	Rear Windscreen Moulding	1		\$51.80 <i>x</i>
	Spare Tyre Lock Nut	1		\$41.80 <i>?</i>
	Spare Tyre Panel	1		\$ 852.80 <i>?</i>
	Spare Tyre Panel Cover	1		\$ 223.10 <i>?</i>
	Rear Towing Hook	1		\$ 194.60 <i>?</i>
<b>SPARE PARTS SUB TOTAL</b>				<b>\$ 16,077.90</b>
<b>LESS 20%</b>				<b>\$ 3,215.58</b>
<b>DISCOUNTED SPARE PARTS TOTAL</b>				<b>\$ 12,862.32</b>

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
				SH 9180L PAGE 2 of 2
	Lim Tien Siong			
	Bootlid ComfortDelGro	1		\$30.00
	Bootlid 65521111	1		\$30.00
	Reverse Sensor	1		\$135.70
	Rear Windscreen Sealant	2	\$46.00	\$92.00
	<b>S/NETT TOTAL</b>			\$287.70
	<b>LESS 10%</b>			\$28.77
	<b>S/NETT TOTAL</b>			\$258.93
	Rear Fender Adv.Sticker RH / LH	2	\$100.00	\$200.00 NETT
	BootLid Adv.Sticker	1		\$100.00 NETT
	Rear Bumper Mat	1		\$50.00 NETT
	<b>SPARE PARTS &amp; OTHERS TOTAL</b>			\$ 13,471.25
	Panel Beating			\$ 3,000.00
	Spray Painting Charge			\$ 2,000.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 120.00
	Remove/Refix Cushion & Upholstery Rear			\$ 120.00
	Remove/Refix Rear Windscreen			\$ 150.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 160.00
				14421.25
	<b>(REAR) ESTIMATE TOTAL</b>			\$ 19,241.25

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanjong 97495244  
WP 28/2/13 2340  
1/3 hour after repair  
Tanjong 97495244  
3-4 days  
To provide fast back vehicle  
To check repair limit.

# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Biddell Road Singapore 579701  
 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

**Workshops**  
 59 Loyang Drive Singapore 508969  
 383 Sin Ming Drive Singapore 575717  
 45 Pandan Road Singapore 609286  
 326 Hill Road Singapore 408648  
 24 Seroko Loop Singapore 758150  
 7 Sungei Kadut Way Singapore 726791  
 501 Yishun Industrial Park A Singapore 758730

Date/Time: 27.02.2023 08:38 Page : 1

Item: ARC Repair TP(CLSO)1

### JOB CARD Sales Order:

JC NO305546613

CUSTOMER  
 COMFORT TRANSPORTATION PTE LTD  
 7010045  
 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65508755 (O)  
 (P)

REGN NO.: <b>SH 9180L</b>	MILEAGE
MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL: <b>I-40</b>	DATE/TIME IN <b>24.02.2023 18:45</b>
YR OF MANU. <b>09.06.2016</b>	TARGET DATE
CHASSIS CODE <b>KMHLB41UMGU090127</b>	COMPLETION DATE/TIME:


UNIT CARD NO.

#### JOB DESCRIPTION

cident Date: 24.02.2023  
 TURE: 3P 24.02.2023

NO LABOR CODE

#### DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

to: SH 9180L LIM TS

Vehicle No.: SH 9180L

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard


24/02/23

## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

### Job Requisition

1. Date: _____	Time Received: _____	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : SH918092 Contact No. : 93407092 Vehicle No. : Make / Model / Colour : HYLAD91140 Email :		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:

7. Location:	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi
9. Preferred Workshop: <input type="checkbox"/> Braddell <input type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Komoco (UBI / Leng Kee) <input checked="" type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____	

10. Odometer Reading : _____	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	 <p># : Cracked X : Dented / : Scatched O : Missing</p>				
Fuel Level : <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>	F		1/4	1/2	3/4	E
F	1/4	1/2	3/4	E		

### Job Attended

12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> OTHERS	<p>Signature of Customer</p>
Name of Driver : JIANG XU	
Vehicle No. : 20454	
Time Dispatch : 9:00	
Time of Arrival : _____	
Time Completed : 9:38	

### Cash Invoice Details (if applicable)

13. Cash Invoice No. : \_\_\_\_\_

### Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

\_\_\_\_\_  
Date Time Signature of Customer

14. WORKSHOP

\_\_\_\_\_  
Name of Attending Staff/Guard Date & Time of Arrival Signature of Attending Staff/Guard