

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315 Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2523J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER (BLUE-DRIVE) LH	NECESSARY	26.60	26.60
1	FRONT FENDER LH	BENT	588.80	588.80
	LESS 20% DISCOUNT		-123.08	-123.08
			492.32	492.32
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADV.STICKER LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	CHECK WIRINGS.	NOT NECESSARY	40.00	-
			740.00	600.00
	GRAND TOTAL		1,332.32	1,192.32
	DECOMMENDED COST OF LUMP SUM DEDAIDS			950.00

(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		950.00

Report Ref No. NS/INC23002203/Twp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.