



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4867Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER COVER	DEFORMED	586.18	586.18
1	FRT BUMPER TOW COVER	NOT NECESSARY	28.38	-
1	FRT GRILLE EMBLEM	NECESSARY	88.00	88.00
1	FRT RUNNING DAYLIGHT RH	NOT NECESSARY	920.00	-
1	HEAD LAMP RH	NOT NECESSARY	2,637.60	-
1	FRONT FENDER SHIELD RH	NOT NECESSARY	198.50	-
1	FRONT FENDER LH	BENT	1,111.93	1,111.93
1	FRONT FENDER EMBLEM	NECESSARY	86.50	86.50
1	FRT BUMPER SIDE RETAINER /RH	NOT NECESSARY	90.75	-
	LESS 25% DISCOUNT		-1,436.96	-468.15
			4,310.88	1,404.46
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING.	NOT NECESSARY	60.00	-
	RESET FRONT WHEEL ALIGNMENT.		60.00	60.00
			1,470.00	910.00
GRAND TOTAL			5,780.88	2,314.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,850.00

Report Ref No. NS/INC23002206/Tqp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.