

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SING		Ref:	CS3/HSB23002209/Wvp3e2
	10 MARINA BOULI	EVARD AY FINANCIAL CENTRE TOWER	Date:	·
	ATTN: HO WINNIE		Code	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHC 3185U	Veh. Inspected	SNG 9069R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04JU8	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	01/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5 DX	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JHMRU1810GX202390	Colour	SILVER
	Odometer	78254 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.	
5.	. General Information			
	Accident Date	24/02/2023	Inspect Date / Time	01/03/2023 (01:07 PM)
	Survey held at TY AUTOCARE SERVICES			
	5033 ANG MO KIO INDUSTRIAL PARK 2 #01-271 SINGAPORE 569536			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days			

Report Ref No. CS3/HSB23002209/Wvp3e2

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser