

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002210/UNP3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00010332300
Claimant Vehicle No :	XD8312S	Insured Vehicle No :	GBE5793L
Date of Loss:	24/02/2023	Nature of Claim: TP	Claim No: SNM23D201529/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD8312S	Engine No:	200012
Make & Model:	IVECO TRAKKER, 12.9 D AT260T41 (A)	Chassis No:	WJME2NSS40C259201
Reg. Date:	28/12/2013 (Man. Year: 2012)	Odometer:	391581 km
Colour:	Gold		
Engine Capacity:	12882 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D/D)
Front Left Side:	AGATE 6 mm	Rear Left Side:	AGATE 6/6/6 mm
Front Right Side:	AGATE 6 mm	Rear Right Side:	AGATE 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,950.00	11,180.00	52,770.00	82.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	1,400.00	5,130.00	78.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	70,480.00	12,580.00	57,900.00	82.15
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	70,480.00	8,800.00	61,680.00	87.51
+ GST 8.00/8.00% (S\$)	5,638.40	704.00	4,934.40	87.51
Nett Amount (S\$)	76,118.40	9,504.00	66,614.40	87.51

INSPECTION

Date of Assignment:	28/03/2023		
Date Inspected:	10/03/2023	Inspected At:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Apr 2023)	
Parts:	N/A	IVECO TRAKKER 12.9 D AT260T41 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8312S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TMA MODULE A ENERGY ABSORB BIG BOX	Distorted	8,980.00 FS	*8,980.00 FS
2	1		*BOTTOM ANGLE CARTRIDGE MASH	Distorted	3,050.00 FS	*1,000.00 FS
3	1		*TOP ANGLE CARTRIDGE ,MASH	Distorted	3,180.00 FS	*1,000.00 FS
4	1		*REAR DIAPHRAGM CARTRIDGE MASH	No such part	4,250.00 FS	*- FS
5	1		*CARTRIDGE TAIL LIGHT ASSY RH	Not Necessary	580.00 FS	*- FS
6	1		*CARTRIDGE TAIL LIGHT ASSY LH	Not Necessary	580.00 FS	*- FS
7	1		*ICC BAR LIGHT ASSY W/COVER FLAP	Not Necessary	980.00 FS	*- FS
8	1		*TMA MODULE C MASH ENERGY ABSORBING BOX	No such part	9,850.00 FS	*- FS
9	1		*CARTRIDGE TUBE ASSY LH MASH ,VEHICLE REINFORCING BAR	Serviceable	15,350.00 FS	*- FS
10	1		*CARTRIDGE TUBE ASSY RH MASH ,VEHICLE REINFORCING BAR	Serviceable	15,350.00 FS	*- FS
11	1		*SET 3M REFLECTIVE STICKERS	Necessary	1,800.00 FS	*200.00 FS
Total Parts (\$\$)						63,950.00 11,180.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE & RENEW ALL ABOVE PARTS	New	3,800.00	1,200.00
2	LABOUR TO CHECK & CONNECT ALL LIGHTING & LAMP & WIRING	New	380.00	0.00
3	TO RUST PROOFING ON AFFECTED AREA	New	850.00	0.00
4	TO SPRAY & PAINTING ON AFFECTED AREA	New	1,500.00	200.00
Gross Labour Cost (\$\$)			6,530.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >