

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002217/RVP3Q2**Date:** 05/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00138302201		
Claimant Vehicle No :	SLN6499P	Insured Vehicle No :	XE7033Z		
Date of Loss:	15/02/2023	Nature of Claim:	TP	Claim No:	SNM23D201450/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN6499P	Engine No:	D4FDHH102929
Make & Model:	KIA CARENS, 1.7 (A)	Chassis No:	KNAHU815VH7178009
Reg. Date:	12/05/2017 (Man. Year: 2017)	Odometer:	104104 km
Colour:	Grey		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,521.00	937.00	7,584.00	89.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,560.00	1,670.00	5,890.00	77.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,081.00	2,607.00	13,474.00	83.79
+ GST 8.00/8.00% (S\$)	1,286.48	208.56	1,077.92	83.79
Nett Amount (S\$)	17,367.48	2,815.56	14,551.92	83.79

INSPECTION

Date of Assignment:	01/03/2023	
Date Inspected:	01/06/2023	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2023)
Parts:	M1-MPV	KIA CARENS 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN6499P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WS SEALANT	Not Necessary	80.00 FS	*- FS
2	1		*RR NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS
3	1		*BODY PNL SEALANT	Not Necessary	80.00 FS	*- FS
4	1		*C&C BADGE	Not Necessary	50.00 FS	*- FS
5	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
6	1		*COVER -RR BUMPER ,UPR	Deformed	691.00 FS	*691.00 FS
7	1		*COVER -RR BUMPER ,LWR	Scratched	226.00 FS	*226.00 FS
8	1		*WIRING HARNESS -R P.A.S	Not Necessary	251.00 FS	*- FS
9	1		*BEAM -RR BUMPER	Not Necessary	367.00 FS	*- FS
10	1		*STAY -RR BUMPER LH	Not Necessary	159.00 FS	*- FS
11	1		*STAY -RR BUMPER RH	Not Necessary	159.00 FS	*- FS
12	1		*BRACKET -RR BUMPER RAIL ,UPR	Not Necessary	5.00 FS	*- FS
13	1		*BRACKER-RR BUMPER LWR ,CTR	Not Necessary	5.00 FS	*- FS
14	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	79.00 FS	*- FS
15	1		*BRACKET ASSY -RR BUMPER SIDE ,LH	Not Necessary	25.00 FS	*- FS
16	1		*BRACKET ASSY -RR BUMPER SIDE ,RH	Not Necessary	25.00 FS	*- FS
17	1		*LAMP ASSY -REAR FOG ,LH	Not Necessary	126.00 FS	*- FS
18	1		*LAMP ASSY -REAR FOG ,RH	Not Necessary	126.00 FS	*- FS
19	4		*ULTRASONIC SENSOR ASSY -P.A.S	Not Necessary	648.00 FS	*- FS
20	2		*HOLDER -BACK WARING SYSTEM OTR	Not Necessary	8.00 FS	*- FS
21	2		*HOLDER -BACK WARING SYSTEM INR	Not Necessary	8.00 FS	*- FS
22	1		*PANEL ASSY -TAIL GATE	Not Necessary	1,218.00 FS	*- FS
23	1		*EMBLEM -CARENS	Not Necessary	36.00 FS	*- FS
24	1		*EMBLEM -CRDI	Not Necessary	29.00 FS	*- FS
25	1		*GARNISH -TAIL GATE ,UPR	Not Necessary	135.00 FS	*- FS
26	1		*MOULDING -CR PIECE	Not Necessary	104.00 FS	*- FS
27	1		*ORNAMENT -KIA	Not Necessary	76.00 FS	*- FS
28	1		*LAMP ASSY -REAR COMB INSIDE ,LH	Not Necessary	773.00 FS	*- FS
29	1		*LAMP ASSY -REAR COMB INSIDE ,RH	Not Necessary	773.00 FS	*- FS
30	1		*LAMP ASSY -REAR COMBINATION ,LH	Not Necessary	770.00 FS	*- FS
31	1		*LAMP ASSY -REAR COMBINATION ,RH	Not Necessary	770.00 FS	*- FS
32	1		*GLASS ASSY -TAIL GATE	Not Necessary	539.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,521.00	937.00
-------------------	----------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER & TAILGATE REPAIR RR END PNL	New	3,840.00	640.00
2	RESPRAY RR BUMPER ,TAILGATE & RR END PNL	New	2,200.00	550.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	280.00	0.00
4	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET	New	280.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	100.00	100.00
6	TO CARRY OUT DIAGNOSITC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
7	REMOVE & REFIT RR WS GLASS	New	280.00	0.00
8	REMOVE & REFIT REVERSE SENSOR	New	120.00	100.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	180.00	0.00
Gross Labour Cost (S\$)			7,560.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >