

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123002221/SNP3E2**Date:** 07/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00001542301
Claimant Vehicle No :	SJW1722D	Insured Vehicle No :	SLR220U
Date of Loss:	14/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D201525/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW1722D	Engine No:	R18A13850606
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68809C200606
Reg. Date:	08/03/2010 (Man. Year: 2009)	Odometer:	177663 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,105.60	2,233.60	6,872.00	75.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,500.00	2,680.00	64.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,285.60	3,733.60	9,552.00	71.90
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	13,285.60	3,000.00	10,285.60	77.42
+ GST 7.00/7.00% (S\$)	929.99	210.00	719.99	77.42
Nett Amount (S\$)	14,215.59	3,210.00	11,005.59	77.42

INSPECTION

Date of Assignment:	01/03/2023	
Date Inspected:	03/03/2023	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW1722D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	956.00 FL	*956.00 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Not Necessary	89.00 FL	*- FL
3	1		*TAILGATE STREAM EMBLEM	Necessary	47.00 FL	*47.00 FL
4	1		*TAILGATE RSZ EMBLEM	Necessary	55.00 FL	*55.00 FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	193.00 FL	*- FL
6	1		*TAILGATE INNER HANDLE	Not Necessary	32.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	479.00 FL	*- FL
8	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
9	1		*TAILGATE LOCK	Not Necessary	119.00 FL	*- FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	45.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Not Necessary	128.00 FL	*- FL
12	1		*TAILGATE WIPER MOTOR	Not Necessary	452.00 FL	*- FL
13	1		*TAILGATE WIPER ARM	Not Necessary	184.00 FL	*- FL
14	1		*TAILGATE WIPER BLADE	Not Necessary	73.00 FL	*- FL
15	1		*REAR BUMPER	Broken	812.00 FL	*668.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	24.00 FL	*- FL
18	1		*REAR BUMPER RH LOWER BRACKET	Not Necessary	18.00 FL	*- FL
19	1		*REAR BUMPER LH LOWER BRACKET	Not Necessary	18.00 FL	*- FL
20	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	22.00 FL	*- FL
21	1		*REAR BUMPER LH SIDE RETAINER	Broken	22.00 FL	*22.00 FL
22	1		*RH TAILLAMP ASSY	Not Necessary	446.00 FL	*- FL
23	1		*RH TAILLAMP PANEL	Not Necessary	164.00 FL	*- FL
24	1		*SET RH TAILLAMP LOCK CLIP	Not Necessary	28.00 FL	*- FL
25	1		*RH TAILLAMP GASKET	Not Necessary	25.00 FL	*- FL
26	1		*LH TAILLAMP ASSY	Cracked	446.00 FL	*446.00 FL
27	1		*LH TAILLAMP PANEL	Not Necessary	164.00 FL	*- FL
28	1		*SET LH TAILLAMP LOCK CLIP	Not Necessary	28.00 FL	*- FL
29	1		*LH TAILLAMP GASKET	Not Necessary	25.00 FL	*- FL
30	1		*END PANEL	Repair	454.00 FL	*- FL
31	1		*END PANEL INNER GARNISH	Cracked	178.00 FL	*178.00 FL
32	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FL	*15.00 FL
33	1		*RH REAR FENDER SPLASH SHIELD	Not Necessary	82.00 FL	*- FL
34	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
35	1		*RH REAR FENDER INNER TRIM BOARD	Not Necessary	382.00 FL	*- FL
36	1		*LH REAR FENDER SPLASH SHIELD	Not Necessary	82.00 FL	*- FL
37	1		*SET LH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
38	1		*LH REAR FENDER INNER TRIM BOARD	Not Necessary	382.00 FL	*- FL
39	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
40	1		*REAR COMPARTMENT PANEL TOP RH COVER	Not Necessary	218.00 FL	*- FL
41	1		*REAR COMPARTMENT PANEL TOP LH COVER	Not Necessary	218.00 FL	*- FL
42	1		*REAR COMPARTMENT PANEL TRIM	Not Necessary	197.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILGATE CENTRE EMBLEM (AFTER MARKET)	Not Necessary	85.00 FS	*- FS
44	1		*EXHAUST SILENCER (AFTER MARKET)	Not Necessary	1,250.00 FS	*- FS
45	1		*EXHAUST SILENCER GASKET (AFTER MARKET)	Not Necessary	67.00 FS	*- FS
46	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
47	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
48	1		*TAILGATE REVERSE CAMERA	Not Necessary	750.00 FS	*- FS
49	1		*SET REAR BUMPER REVERSE SENSOR	Faulty	350.00 FS	*200.00 FS
50	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*60.00 FS
51	1		*LH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS
52	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS
53	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
54	1		*SET RH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,659.00	2,717.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,553.40	483.40
Total Parts (\$)	9,105.60	2,233.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,600.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	40.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	80.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	30.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	120.00	50.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
9	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO ASSIST REPAIR	New	280.00	40.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	0.00
Gross Labour Cost (\$)			4,180.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >