

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23002225/KWY3Q2**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	TAN XUE LI	Policy No:	SPCM1000000487	
Date of Loss:	28/02/2023	Nature of Claim:	OD	Claim No: SMN184A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN184A		
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 G (A)	Engine No:	1NZR469830
Reg. Date:	23/07/2019 (Man. Year: 2016)	Chassis No:	NHP1707071436
Colour:	Metallic Pearl White	Odometer:	97066 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 3 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,957.70	4,341.70	616.00	12.43
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	1,900.00	1,680.00	220.00	11.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,897.70	6,061.70	836.00	12.12
Approved Total (Overridden) (S\$)		4,250.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	6,897.70	2,250.00	4,647.70	67.38
+ GST 8.00/8.00% (S\$)	551.82	180.00	371.82	67.38
Nett Amount (S\$)	7,449.52	2,430.00	5,019.52	67.38

INSPECTION

Date of Assignment:	01/03/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	02/03/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN184A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*1 PC FRT BUMPER (WCP)	Bent / Cracked	180.00 F	*180.00 F
2	1	*2 PCS FRT BUMPER SIDE RETAINERS @45/PC (WCP)	Distorted	90.00 F	*90.00 F
3	1	*6 PCS FRT BUMPER TOP RUBBER CLIPS @2/PC (WCP)	Necessary	12.00 F	*12.00 F
4	1	*1 PC FRT BUMPER LOGO (WCP)	Not Necessary	40.00 F	*- F
5	1	*1 PC FRT BUMPER TOP BEAM (WCP)	Distorted	50.00 F	*50.00 F
6	1	*2 PCS HEADLAMPS @380/PC (WCP)	O/S MtgCracked/N/S Serviceable	760.00 F	*380.00 F
7	1	*1 PC FRT SUPPORT PANEL (WCP)	Buckled	450.00 F	*450.00 F
8	1	*1 PC FRT BRACE PANEL (WCP)	Bent	60.00 F	*60.00 F
9	1	*1 PC AIR-CON CONDENSER (WCP)	Punctured	500.00 F	*500.00 F
10	1	*1 PC INVERTER RADIATOR (WCP)	Punctured	400.00 F	*400.00 F
11	1	*1 PC BONNET (WCP)	Bent	280.00 F	*280.00 F
12	1	*1 PC BONNET LOCK (WCP)	Distorted	55.00 F	*55.00 F
13	1	*2 PCS BONNET HINGES @40/PC (WCP)	Distorted	80.00 F	*80.00 F
14	1	*1 PC FRT SUPPORT TOP AIR-GUARD (WCP)	Dented	80.00 F	*80.00 F
15	1	*1 PC FRT RH FENDER EMBLEM (HYBRID) (WCP)	Necessary	40.00 F	*40.00 F
16	1	*1 PC FRT BUMPER REINFORCEMENT (WCP)	Repair	140.00 F	*- F
Supplementary #1					
17	1	*1 PC RADIATOR (WCP)	Punctured	650.00 F	*650.00 F
18	1	*1 PC FRT GRILLE (WCP)	Cracked	350.00 F	*350.00 F
19	1	*1 PC AIR FILTER HOUSING (WCP)	Cracked	290.00 F	*290.00 F

F=Franchise part.

Sub Total (\$\$)		4,507.00	3,947.00
+ Margin on L,N Items 10.00/10.00% (\$\$)		450.70	394.70
Total Parts (\$\$)		4,957.70	4,341.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NUMBER PLATE (CRACKED)	40.00	40.00
Sub Total (\$\$)			40.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,BONNET & ATTACHMENT,RADIATOR,FRT FENDERS,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT CHASSIS,FRT RH FENDER INNER PANEL AND REALIGN THE SAME	New	800.00	680.00
2	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
3	PUTTY & RESPRAY ON FRT RH DOOR,FRT BUMPER,REINFORCEMENT AND BEAM,BONNET AND HINGES,FRT SUPPORT PANEL,FRT RH FENDER INNER PANEL	New	1,000.00	900.00
Gross Labour Cost (\$\$)			1,900.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >