



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1660B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP	MTG CRACKED	1,704.30	1,704.30
1	FRONT BUMPER RETAINER	SERVICEABLE	45.00	-
1	FRONT BUMPER SENSOR	SERVICEABLE	280.00	-
	LESS 20% DISCOUNT		-405.86	-
	LESS 25% DISCOUNT		-	-426.08
			1,623.44	1,278.22
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER (SN)	BUCKLED/DENTED	580.50	580.50
1	FRONT BUMPER LOWER LID (SN)	BUCKLED/DISTORTED	590.00	359.00
			1,170.50	939.50
	<u>LABOUR</u>			
	SPRAY PAINTING.		250.00	220.00
	LABOUR CHARGES TO RENEW ABOVE PARTS.		300.00	200.00
			550.00	420.00
	GRAND TOTAL		3,343.94	2,637.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS/LIP23002251/Kvy3m4

MARKET VALUE: \$75,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,855.00=NETT VALUE: \$49,145.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.