

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III23000058/RVY3M4-1**Date:** 10/04/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000637\_02

**Claimant Vehicle No :** FBF2200X**Insured Vehicle No :** FBN7880H

Date of Loss: 29/12/2022

Nature of Claim: TP

Claim No: MFL2023D0000225

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBF2200X**

Make &amp; Model: YAMAHA NMAX155, 155cc ABS CVT

Engine No: G3L8E0324121

Reg. Date: 06/04/2021 (Man. Year: 2021)

Chassis No: MH3SG5680MK056621

Colour: Black

Odometer: 41991 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13

Rear Tyre Size: 130/70-13

Front Left Side: Pirelli 3 mm

Rear Left Side: Pirelli 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,514.00	3,391.80	5,122.20	60.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	900.00	700.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,114.00</b>	<b>4,291.80</b>	<b>5,822.20</b>	<b>57.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,114.00</b>	<b>3,400.00</b>	<b>6,714.00</b>	<b>66.38</b>

INSPECTION

Date of Assignment: 01/03/2023

Date Inspected: 03/01/2023 Inspected At:

Friendship Motor Company (lane 2) (HQ)

Blk 1005 Bukit Merah Lane 2

#01-18 Singapore 159761

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 10 Apr 2023)	
<b>Parts:</b>	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBF2200X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL RIM	Repair	520.00 F	*- FL
2	1		*FRONT BRAKE DISC	Dented/Warped	189.00 F	*75.00 FL
3	1		*FRONT MUDGUARD	Broken	215.00 F	*180.00 FL
4	1		*FRONT FORK	Dented/Warped	640.00 F	*640.00 FL
5	1		*FRONT UNDER BRACKET	Dented	102.00 F	*102.00 FL
6	1		*STEERING CONE	Dented	89.00 F	*80.00 FL
7	1		*HEADLAMP	Cracked	285.00 F	*285.00 FL
8	1		*HEADLAMP BRACKET	Dented	62.00 F	*62.00 FL
9	2		*SIGNAL LAMP	Not Necessary	196.00 F	*- FL
10	1		*HEADLAMP LOWER GARNISH	Dented	95.00 F	*85.00 FL
11	1		*SIGNAL LAMP GARNISH	Dented (1Piece Only)	90.00 F	*45.00 FL
12	1		2PIECES *HEADLAMP COWLING	Dented	105.00 F	*105.00 FL
13	1		*FRONT VISOR	Missing/Dislodged	89.00 F	*72.00 FL
14	1		*FRONT VISOR GARNISH	Dented	65.00 F	*65.00 FL
15	1		*FRONT VISOR GARNISH STAY	Not Necessary	42.00 F	*- FL
16	1		*HEADLAMP SIDE PANEL	Dented (1Piece Only)	96.00 F	*48.00 FL
17	1		2PIECES *FRONT SPLASH SHIELD	Dented	63.00 F	*50.00 FL
18	1		*FRONT SPLASH SHIELD BODY GARNISH	Dented	58.00 F	*58.00 FL
19	1		*HANDLE BAR	Dented	215.00 F	*150.00 FL
20	1		*HANDLE GRIP	Necessary (1Piece Only)	76.00 F	*38.00 FL
21	1		2PIECES *HANDLE BALANCER	Sliced (1Piece Only)	72.00 F	*36.00 FL
22	1		2PIECES *LEVER	Sliced (1Piece Only)	170.00 F	*52.00 FL
23	1		*R/H CENTRE BODY GARNISH (NOT NECESSARY)	Old Damaged	103.00 F	*- FL
24	1		*R/H STEP GARNISH (NOT NECESSARY)	Old Damaged	128.00 F	*- FL
25	1		*R/H STEP GARNISH LOWER GARNISH (NOT NECESSARY)	Old Damaged	106.00 F	*- FL
26	1		*R/H STEP GARNISH SEAL (NOT NECESSARY)	Old Damaged	45.00 F	*- FL
27	1		*R/H REAR FOOT REST (NOT NECESSARY)	Old Damaged	72.00 F	*- FL
28	1		*R/H REAR BODY GARNISH (NOT NECESSARY)	Old Damaged	89.00 F	*- FL
29	1		*R/H REAR BODY GARNISH COVER (NOT NECESSARY)	Old Damaged	75.00 F	*- FL
30	1		*ENGINE INNER COVER (NOT NECESSARY)	Old Damaged	122.00 F	*- FL
31	1		*ENGINE OUTER COVER	Dented	138.00 F	*138.00 FL
32	1		*ENGINE LOWER COVER	Dented	135.00 F	*135.00 FL
33	1		*SIDE STAND	Dented	85.00 F	*85.00 FL
34	1		*MAIN STAND	Dented	92.00 F	*92.00 FL
35	2		*MIRROR	Sliced	164.00 F	*110.00 FL
36	1		*N/S STEP GARNISH	Dented	128.00 F	*85.00 FL
37	1		*N/S STEP LOWER GARNISH	Dented	106.00 F	*106.00 FL
38	1		*N/S STEP GARNISH SEAL	Dented	45.00 F	*45.00 FL
39	1		*N/S CENTRE BODY GARNISH	Dented	89.00 F	*89.00 FL
40	1		*N/S CENTRE BODY GARNISH COVER	Dented	65.00 F	*65.00 FL
41	1		*N/S REAR FOOT REST	Sliced	72.00 F	*72.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*N/S REAR BODY GARNISH	Dented	102.00 F	*102.00 FL
43	1		*REAR MUDGUARD	Not Necessary	98.00 F	*- FL
44	1		*RADIATOR COVER	Not Necessary	85.00 F	*- FL
45	1		*EXHAUST MUFFLER	Not Necessary	620.00 F	*- FL
46	1		*EXHAUST HEAT SHIELD	Not Necessary	86.00 F	*- FL
47	1		*REAR WHEEL RIM	Serviceable	550.00 F	*- FL
48	1		*FRONT BRAKE CALIPER	Serviceable	265.00 F	*- FL
49	1		*FRONT VIDEO CAMERA	Broken	400.00 FS	*150.00 FS
50	1		*FRONT TYRE	Not Necessary	200.00 FS	*- FS
51	1		*FRONT NUMBER PLATE	Missing/Dislodged	35.00 FS	*25.00 FS
52	1		*REAR BOX	Dented/Cut	500.00 FS	*200.00 FS
53	1		*REAR BOX BRACKET	Repair	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,514.00	3,727.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	335.20
Total Parts (S\$)	8,514.00	3,391.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	660.00	450.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	600.00	250.00
3	TO ALIGN MAIN BODY FRAME	New	280.00	200.00
4	TRANSPORTATION CHARGES	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >