

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB22010279/DVY3E2-1**Date:** 06/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : FS6180C **Insured Vehicle No :** SLT4716U
 Date of Loss: 09/10/2022 Nature of Claim: TP Claim No: MFL2022D0005668

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FS6180C**
 Make & Model: HONDA CB400ASFYJ, 399cc Engine No: NC23E2013541
 Reg. Date: 25/09/2000 (Man. Year: 2000) Chassis No: NC391013540
 Colour: Silver Odometer: 0 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60-17 Rear Tyre Size: 160/60-17
 Front Left Side: Timsun 5 mm Rear Left Side: Timsun 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,976.00	2,848.00	2,128.00	42.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	700.00	580.00	45.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,256.00	3,548.00	2,708.00	43.29
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	6,256.00	2,850.00	3,406.00	54.44

INSPECTION

Date of Assignment: 01/03/2023
 Date Inspected: 17/10/2022 Inspected At: V MAPS MOTOR (HQ)
 10 KAKI BUKIT RD 2 #01-36
 Singapore 417868
 Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Mar 2023)	
Parts:	N/A	HONDA CB400ASFYJ 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS6180C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK	Dented / Warped	680.00 F	*680.00 FL
2	1		*UNDER BRACKET	Dented	102.00 F	*102.00 FL
3	1		*STEERING CONE W/BEARING	Necessary	89.00 F	*89.00 FL
4	1		*FRONT MUDGUARD	Repair	198.00 F	*- FL
5	1		*FRONT WHEEL RIM	Serviceable	585.00 F	*- FL
6	1		*HANDLE BAR	Bent	210.00 F	*210.00 FL
7	2		*HANDLE GRIP	Not Necessary	80.00 F	*- FL
8	1		*R/H MIRROR	Sliced	82.00 F	*82.00 FL
9	1		*BRAKE LEVER	Sliced	85.00 F	*85.00 FL
10	1		*R/H HANDLE BALANCER	Sliced	45.00 F	*45.00 FL
11	1		*FUEL TANK	Repair	698.00 F	*- FL
12	1		*HEADLAMP	Dented	285.00 F	*285.00 FL
13	1		*HEADLAMP BRACKET	Dented	98.00 F	*98.00 FL
14	1		*R/H FRONT FOOT REST	Sliced	78.00 F	*78.00 FL
15	1		*R/H REAR FOOT REST	Sliced	78.00 F	*78.00 FL
16	1		*BRAKE PEDAL	Sliced	82.00 F	*82.00 FL
17	1		*R/H ENGINE PROTECTOR BAR	Dented / Sliced	126.00 F	*126.00 FL
18	1		*R/H REAR SIGNAL LAMP	Sliced	95.00 F	*95.00 FL
19	1		*EXHAUST MUFFLER	Dented / Sliced	785.00 F	*785.00 FL
20	1		*FRONT NUMBER PLATE	Not Necessary	35.00 FS	*- FS
21	1		*REAR BOX	Sliced	300.00 FS	*220.00 FS
22	1		*REAR BOX BRACKET	Not Necessary	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,976.00	3,140.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	292.00
Total Parts (\$\$)	4,976.00	2,848.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	580.00	250.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	400.00	250.00
3	TO ALIGN MAIN BODY FRAME	New	300.00	200.00
Gross Labour Cost (S\$)			1,280.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >