

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 6180J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	744.20	-
1	FRONT HEADLAMP RH	CRACKED	535.20	535.20
1	FRONT BUMPER	MTG CRACKED	586.80	485.20
1	FRONT BUMPER RETAINER RH	DISTORTED	76.90	76.90
1	FRONT FOGLAMP GARNISH RH	SERVICEABLE	84.40	-
1	FRONT RH FENDER	BENT	688.60	581.00
1	"WT-I" EMBLEM	NECESSARY	38.40	38.40
1	FRONT RH FENDER INNER LINER	SERVICEABLE	208.50	-
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	1,310.80	-
1	SIDE MIRROR ASSY RH	CRACKED / JAMMED	1,446.60	680.50
	LESS 25% DISCOUNT		-1,430.10	-599.30
			4,290.30	1,797.90
	SPECIAL NETT ITEMS			
1	FRONT FENDER INNER LINER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT FOGLAMP RH (SN)	SERVICEABLE	180.00	-
			240.00	60.00
	<u>LABOUR</u>			
	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM.		60.00	20.00
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	650.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT RH DOOR.		1,000.00	500.00
			1,860.00	1,170.00
	GRAND TOTAL		6,390.30	3,027.90

Report Ref No. CS/AGI23002262/Kvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI23002262/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser