

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002265/KCP3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00133062203
Claimant Vehicle No :	GBH9804Y	Insured Vehicle No :	GBB5409M
Date of Loss:	28/02/2023	Nature of Claim:	TP
		Claim No:	SNM23D201547/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH9804Y	Engine No:	YD25038198B
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Chassis No:	JN1MC2E26Z0030672
Reg. Date:	19/11/2018 (Man. Year: 2018)	Odometer:	119581 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Triangle 3 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	Triangle 3 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,989.10	6,768.80	3,220.30	32.24
Miscellaneous Items	30.00	20.00	10.00	33.33
Labour	6,290.00	5,650.00	640.00	10.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,309.10	12,438.80	3,870.30	23.73
Approved Total (Overridden) (S\$)		12,400.00		
(S\$)	16,309.10	12,400.00	3,909.10	23.97
+ GST 8.00/8.00% (S\$)	1,304.73	992.00	312.73	23.97
Nett Amount (S\$)	17,613.83	13,392.00	4,221.83	23.97

INSPECTION

Date of Assignment:	02/03/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	06/03/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	12.0 days		

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Jul 2023)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9804Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT LH DOOR	Bent	780.00 F	*780.00 FL
2	1		*1 PC FRT LH DOOR SIDE MIRROR ASSY	Broken	350.00 F	*350.00 FL
3	1		*1 PC FRT LH DOOR GLASS	Cut	340.00 F	*340.00 FL
4	1		*1 PC FRT LH DOOR OUTER HANDLE	Dented	88.00 F	*88.00 FL
5	1		*1 PC FRT LH DOOR INNER LOCK	Dented	160.00 F	*160.00 FL
6	1		*1 PC FRT LH DOOR INNER RUBBER	Cut	90.00 F	*90.00 FL
7	1		*1 PC LH CENTRE PANEL OUTER	Bent	980.00 F	*980.00 FL
8	1		*1 PC LH SLIDING DOOR	Bent	800.00 F	*800.00 FL
9	1		*1 PC LH SLIDING DOOR OUTER HANDLE	Dented	90.00 F	*90.00 FL
10	1		*1 PC LH SLIDING DOOR ROLLER TRUCK	Distorted	450.00 F	*450.00 FL
11	1		*1 PC LH SLIDING DOOR INNER LOCK	Dented	170.00 F	*170.00 FL
12	1		*1 PC LH SLIDING DOOR INNER RUBBER	Cut	130.00 F	*130.00 FL
13	1		*1 PC LH SLIDING DOOR INNER TRIM BOARD	Cracked	280.00 F	*280.00 FL
14	1		*1 PC REAR LH SIDE PANEL	Bent	1,050.00 F	*1,050.00 FL
15	1		*1 PC REAR LH SIDE PANEL INNER TRIM BOARD	Serviceable	260.00 F	*- FL
16	1		*1 PC FRT LH DOOR GLASS REGULATOR	Distorted	105.00 F	*105.00 FL
17	1		*1 PC FRT LH DOOR GLASS REGULATOR MOTOR	Serviceable	360.00 F	*- FL
18	1		*1 PC FRT RH DOOR	Bent	790.00 F	*790.00 FL
19	1		*1 PC FRT RH STEP TRAY GARNISH	Dented	68.00 F	*68.00 FL
20	1		*1 PC FRT BUMPER	Buckled / Cut	300.00 F	*300.00 FL
21	1		*1 PC FRT BUMPER RH SIDE RETAINER	Distorted	85.00 F	*85.00 FL
Supplementary #1						
22	1		*1 PC LH DOOR CENTRE PILLAR INNER	Bent	750.00 F	*750.00 FL
23	1		*1 PC LH DOOR CENTRE PILLAR WHEEL MUDGUARD	Dented	45.00 F	*45.00 FL
24	1		*1 PC TURBO COOLER COVER	Cracked	105.00 F	*105.00 FL
25	1		*1 PC SLIDING DOOR SWITCH	Cracked	105.00 F	*105.00 FL
26	1		*1 PC FRT GRILLE	Mtg Cracked	350.00 F	*350.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	9,081.00	8,461.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,692.20
+ Margin on L,N Items 10.00/0.00% (\$)	908.10	0.00
Total Parts (\$)	9,989.10	6,768.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Supplementary #1</u>				
1	1	LH SIDE PANEL GLASS GUM (NECESSARY)	30.00	20.00
Sub Total (\$\$)			30.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING (BY OWNER)	New	80.00	80.00
2	REMOVE & REFIX FRT BOTH DOOR, KNOCK & REPAIR FRT BOTH DOOR PILLARS, REMOVE & REFIX LH SLIDING DOOR, CUT, WELD & RENEW REAR LH SIDE PANEL,CENTRE DOOR PILLAR OUTER, KNOCK & REPAIR REAR LH SIDE INNER PANEL,CENTRE PILLAR INNER AND REALIGN THE SAME	New	2,200.00	2,000.00
3	REMOVE & REFIX FRT BOTH DOOR GLASS	New	120.00	120.00
4	REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET	New	100.00	80.00
5	PUTTY & REPSPRAY ON FRT BOTH DOORS, LH SLIDING DOOR, CENTRE PILLAR, REAR LH SIDE PANEL INNER & OUTER	New	1,500.00	1,100.00
6	RUSTPROOFING	New	90.00	90.00
7	TO REPAINT ADVERTISEMENT	New	2,100.00	2,100.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
8	REMOVE AND REFIT LH SIDE PANEL GLASS	New	100.00	80.00
Gross Labour Cost (\$\$)			6,290.00	5,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >