



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD		Ref: CS3/HSB23002269/Tnp3e2	
10 MARINA BOULEVARD		Date: 15/05/2023	
#48-01 MARINA BAY FINANCIAL CENTRE TOWER			
2SINGAPORE 018983			
ATTN: WINNIE HO		Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 9311T	Veh. Inspected	YQ 3301B
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S3M04JSI	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	02/03/2023
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI CANTER FEB21	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	FEB21EA35117	Colour	WHITE
Odometer	94419 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/85 R15	KENDA	6 mm
L/H Front Tyre	195/85 R15	KENDA	6 mm
R/H Rear Tyre	195/85 R15 (D)	KENDA	6/6 mm
L/H Rear Tyre	195/85 R15 (D)	KENDA	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	22/02/2023	Inspection Date	03/03/2023
Survey held at	4 PENJURU CLOSE		
Repairer	AAK LOGISTICS SERVICES PL		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	