

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23002288/HVY3M4  
**Date:** 31/03/2023**REFERENCE**

Insured/Claimant:	LAM FAIR FONG	Policy No:	SP2003930241-01	
Date of Loss:	27/02/2023	Nature of Claim:	OD	Claim No: 202332005796

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLW4758H</b>	Engine No:	G4FGJU134373
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Chassis No:	KMHD841CMJU628483
Reg. Date:	13/02/2018 (Man. Year: 2018)	Odometer:	79635 km
Colour:	Beige		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,941.00	4,386.80	2,554.20	36.80
Miscellaneous Items	215.00	60.00	155.00	72.09
Labour	2,700.00	1,300.00	1,400.00	51.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,856.00</b>	<b>5,746.80</b>	<b>4,109.20</b>	<b>41.69</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>788.48</b>	<b>459.74</b>	<b>328.74</b>	<b>41.69</b>
<b>Nett Amount (S\$)</b>	<b>10,644.48</b>	<b>6,206.54</b>	<b>4,437.94</b>	<b>41.69</b>

**INSPECTION**

Date of Assignment:	02/03/2023	Present Location:	Century Motors Pte Ltd (HQ) Century Motors Pte Ltd (HQ)
Date Inspected:	03/03/2023	Inspected At:	2 Pandan Crescent, Inchage Centre Level 10 Singapore 128462
Estimated Period of Repair:	5.0 days		

**Adjuster:** Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2023)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW4758H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT WINDSCREEN</b> (WCP)	Not Necessary	600.00 F	*- F
2	1		<b>*FRONT WINDSCREEN MOULDING</b> (WCP)	Not Necessary	70.00 F	*- F
3	1		<b>*HEAD LAMP LH</b> (WCP)	Crushed	540.00 F	*540.00 F
4	1		<b>*HEAD LAMP SUPPORT LH</b> (WCP)	Cracked	20.00 F	*20.00 F
5	1		<b>*FRONT BONNET</b> (WCP)	Buckled	750.00 F	*750.00 F
6	1		<b>*BONNET LOCK</b> (WCP)	Bent	90.00 F	*90.00 F
7	1		<b>*BONNET HINGE LH</b> (WCP)	Bent	45.00 F	*45.00 F
8	1		<b>*BONNET HINGE RH</b> (WCP)	Bent	45.00 F	*45.00 F
9	1		<b>*FRONT BUMPER</b> (WCP)	Cracked	420.00 F	*420.00 F
10	1		<b>*FRONT BUMPER INNER BRACKET LH</b> (WCP)	Cracked	25.00 F	*18.00 F
11	1		<b>*FRONT BUMPER UPPER BRACKET LH</b> (WCP)	Not Necessary	25.00 F	*- F
12	1		<b>*FRONT BUMPER SIDE RETAINER</b> (WCP)	Not Necessary	25.00 F	*- F
13	1		<b>*FRONT BUMPER SPONGE</b> (WCP)	Not Necessary	90.00 F	*- F
14	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Not Necessary	230.00 F	*- F
15	1		<b>*FRONT BUMPER AIR INTAKE COVER LH</b> (WCP)	Not Necessary	20.00 F	*- F
16	1		<b>*FRONT FENDER LH</b> (WCP)	Repair	420.00 F	*- F
17	1		<b>*FRONT FENDER INNER SHIELD LH</b> (WCP)	Not Necessary	60.00 F	*- F
18	1		<b>*FRONT FOG LAMP LH</b> (WCP)	Not Necessary	130.00 F	*- F
19	1		<b>*FRONT FOG LAMP COVER LH</b> (WCP)	Not Necessary	60.00 F	*- F
20	1		<b>*FRONT GRILLE</b> (WCP)	Cut	420.00 F	*420.00 F
21	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Bent	460.00 F	*460.00 F
22	1		<b>*RADIATOR</b> (WCP)	Dented/Bent	300.00 F	*300.00 F
23	1		<b>*CONDENSER</b> (WCP)	Not Necessary	340.00 F	*- F
24	1		<b>*AIR INTAKE DUCT</b> (WCP)	Not Necessary	60.00 F	*- F
25	1		<b>*AIR FILTER HOUSING ASSY</b> (WCP)	Not Necessary	125.00 F	*- F
26	1		<b>*FUSE BOX UPPER COVER</b> (WCP)	Cracked	50.00 F	*50.00 F
27	1		<b>*SIDE MEMBER BRACKET LH</b> (WCP)	Not Necessary	40.00 F	*- F

### Supplementary #1

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		<b>*FAN COWLING</b> (WCP)	Cracked	100.00 F	*100.00 F
29	1		<b>*HEADLAMP BRACKET LH</b> (WCP)	Not Necessary	20.00 F	*- F
30	1		<b>*HEADLAMP RH</b> (WCP)	Cut	540.00 F	*540.00 F
31	1		<b>*GRILLE UPPER GARNISH</b> (WCP)	Cut	75.00 F	*75.00 F
32	1		<b>*BONNET INSULATOR</b> (WCP)	Torn	115.00 F	*115.00 F

F=Franchise part.

<b>Sub Total (\$)</b>	<b>6,310.00</b>	<b>3,988.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	631.00	398.80
<b>Total Parts (\$)</b>	<b>6,941.00</b>	<b>4,386.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>AIRCOND GAS</b> (NOT NECESSARY)	60.00	0.00
2	1	<b>FRONT BUMPER CLIPS</b> (NECESSARY)	30.00	30.00
3	1	<b>FRONT NUMBER PLATE &amp; HOLDER</b> (NOT NECESSARY)	35.00	0.00
4	1	<b>RADIATOR COOLANT</b> (NECESSARY)	30.00	30.00
5	1	<b>WINDSCREEN SEALANT</b> (NOT NECESSARY)	60.00	0.00
<b>Sub Total (S\$)</b>			<b>215.00</b>	<b>60.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>LABOUR FOR PANEL BEATING</b>	New	1,400.00	600.00
2	<b>LABOUR FOR SPRAY PAINTING</b>	New	1,200.00	700.00
3	<b>TO REMOVE &amp; REFIT FRONT WINDSCREEN</b>	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,700.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**