



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1697Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER WITH LOWER BLACK	DENTED	693.10	693.10
2	REAR BUMPER SIDE HOLDER - LH / RH @\$47.10	NECESSARY	94.20	94.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
2	REAR BUMPER REFLECTORS - LH / RH @\$61.30	NOT NECESSARY	122.60	-
1	REAR BUMPER REINFORCEMENT	BENT	596.20	596.20
1	REAR BUMPER LOWER CENTER GRILLE (BLACK)	NOT NECESSARY	127.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	447.50	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	87.80	-
1	BOOTLID	DENTED / WARPED	4,380.00	4,380.00
1	BOOTLID XTRAIL WORDINGS	NECESSARY	94.00	94.00
1	BOOTLID GLASS MOULDING	NECESSARY	106.30	106.30
1	BOOTLID NISSAN LOGO	NOT NECESSARY	94.00	-
1	BOOTLID RUBBER	NOT NECESSARY	140.80	-
2	REAR BUMPER REINFORCEMENT BRACKET - LH / RH @ \$196.60 (ADDITIONAL)	BENT	393.20	393.20
	LESS 10% DISCOUNT		-742.67	-638.70
			6,684.03	5,748.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER SENSOR (4PCS) (SN)	SHORTED	400.00	200.00
			400.00	200.00
<b><u>LABOUR</u></b>				
	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	480.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS (BUMPER 3 COLOUR).		900.00	600.00
	TO CHECK WIRING.		40.00	20.00
	TO REMOVE, REFIT REAR GLASS.		180.00	120.00
	TO REMOVE, REFIT REAR GARNISH TO FACILITATE REPAIR.		150.00	60.00
	TO REMOVE, REPLACE REAR BUMPER SENSOR.		90.00	50.00

Report Ref No. CS/SMO23002289/Uny3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
			2,220.00	1,330.00
<b>GRAND TOTAL</b>			<b>9,304.03</b>	<b>7,278.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,800.00</b>

Report Ref No. CS/SMO23002289/Uny3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.