



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 3104R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LEFT FRONT DOOR SIDE MIRROR HOUSING	DAMAGED	960.00	960.00
1	LEFT FRONT DOOR SIDE MIRROR SIDE COVER TOP	MISSING	373.00	105.00
1	LEFT FRONT DOOR SIDE COVER LOWER	NOT NECESSARY	103.00	-
1	LEFT FRONT DOOR GLASS	NOT NECESSARY	234.00	-
	LESS 10% DISCOUNT		-	-106.50
			1,670.00	958.50
	<b><u>LABOUR</u></b>			
	TO RUSTPROOF.	NOT NECESSARY	100.00	-
	TO DISMANTLE / RENEW SIDE MIRROR.	NOT NECESSARY	150.00	-
	TO DISMANTLE / RENEW ACCIDENT PORTION.		500.00	200.00
	TO SPRAY PAINT.		500.00	300.00
			1,250.00	500.00
<b>GRAND TOTAL</b>			<b>2,920.00</b>	<b>1,458.50</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,150.00</b>
---	--	--	-----------------

Report Ref No. CS/LIP23002299/Awy3e2

MARKET VALUE: \$35,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,271.00=NETT VALUE: \$14,729.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.