



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5698Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED / DEFORMED	933.20	645.10
2	REAR BUMPER SIDE HOLDER - LH / RH @\$105.60	NOT NECESSARY	211.20	-
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR BUMPER FOAM (NPA)	NOT FITTED	-	-
1	REAR BUMPER REINFORCEMENT	DENTED	480.20	480.20
1	REAR BUMPER REFLECTORS - LH	NOT NECESSARY	72.20	-
1	REAR BOOTLID	DENTED / BENT	1,433.90	1,433.90
2	REAR BOOT HINGE - LH / RH @\$211.40	NOT NECESSARY	422.80	-
13	REAR BOOT INSULATOR CLIPS @\$5.80	NOT NECESSARY	75.40	-
1	REAR BOOT OUTER CHROME	CRACKED	502.50	502.50
1	REAR BOOT CAMRY WORDINGS	NECESSARY	75.60	75.60
1	REAR BOOT LOGO	NECESSARY	72.20	72.20
1	REAR BOOT 2.0 WORDING	NECESSARY	71.50	71.50
1	REAR BOOT LAMP - LH	NOT NECESSARY	637.50	-
1	REAR BOOT RUBBER	NOT NECESSARY	308.10	-
1	REAR BOOT TOP LOCK	NOT NECESSARY	527.40	-
1	TAIL LAMP - LH	NOT NECESSARY	621.00	-
1	TAIL LAMP CLIPS - LH	NOT NECESSARY	5.50	-
	LESS 25% DISCOUNT		-1,626.30	-834.00
			4,878.90	2,502.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE WITH CASING (SPECIAL) (SN)	SERVICEABLE	70.00	-
1	SET REAR BUMPER SENSOR (SN)	MALFUNCTION	220.00	200.00
			290.00	200.00
<b><u>LABOUR</u></b>				
	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS.		550.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		750.00	600.00
	TO CHECK WIRING.		40.00	20.00
	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR.		150.00	60.00

Report Ref No. CS/AWA23002304/Uvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.		60.00	30.00
			1,550.00	1,110.00
GRAND TOTAL			6,718.90	3,812.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/AWA23002304/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.