

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23002305/AWP3M4**Date:** 13/03/2023**REFERENCE**

Insured/Claimant: KOO JIA NING Policy No: DMPCNSNA00155742201
Date of Loss: 01/03/2023 Nature of Claim: OD Claim No: SNM23D201597/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9934K**
Make & Model: VOLVO S80, 1.6 D 2 (A) Engine No: D4162T4181383
Reg. Date: 27/06/2015 (Man. Year: 2015) Chassis No: YV1AS84ABF1191941
Colour: Silver Odometer: 0 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$47,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	0.00	500.00	-500.00	
Nett Amount (\$\$)	0.00	-500.00	500.00	

INSPECTION

Date of Assignment: 02/03/2023 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME MOTOR PTE LTD
Date Inspected: 03/03/2023 Inspected At: 1 KAKI BUKIT AVE 6
#02-15 (AUTOBAY @KAKI BUKIT)
SINGAPORE 417883
Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$47,000.00
OMV :	\$29,466.00
PARF Rebate (1) :	\$10,951.00
Quota Premium Paid :	\$67,601.00
COE Rebate (2) :	\$15,642.00
Total Rebate (1) + (2) = :	\$26,593.00

The total amount incurred will be Market Value \$47,000.00 minus Total Rebate \$26,593.00 = \$20,407.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	143	VOLVO S80 1.6 D 2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9934K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >