



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 81E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	DEFORMED	300.00	300.00
2	FRONT BUMPER RETAINER @\$90EA (WCP)	NOT NECESSARY	180.00	-
1	FRONT BUMPER LOWER GRILLE (WCP)	DEFORMED	100.00	100.00
1	FRONT BUMPER REFORCEMENT (WCP)	BENT	290.00	290.00
1	HORN (NPA)	NOT NECESSARY	-	-
1	FRONT CENTER GRILLE/CHROME (WCP)	CRACKED	480.00	480.00
1	EMBLEM (WCP)	NECESSARY	150.00	150.00
1	FRONT SUPPORT PANEL (WCP)	TO REPAIR SEE LABOUR	840.00	-
1	BACE PANEL (WCP)	BENT	230.00	230.00
2	RADIATOR SIDE GARNISH @\$120EA (WCP)	DEFORMED	240.00	240.00
10	CLIPS @\$4EA (WCP)	NOT NECESSARY	40.00	-
1	UNDER ENGINE COVER (WCP)	DEFORMED	450.00	450.00
1	SUPPORT TOP GARNISH (WCP)	DEFORMED	120.00	120.00
2	FRONT HEADLAMP @\$360EA (WCP)	CRACKED	720.00	720.00
1	FRONT FENDER LH (WCP)	NOT NECESSARY	360.00	-
1	FRONT RADIATOR (WCP)	NOT NECESSARY	1,440.00	-
1	AIR CON CONDENSOR (WCP)	NOT NECESSARY	780.00	-
1	FAN COWLING (WCP)	NOT NECESSARY	180.00	-
1	FAN BLADE (WCP)	NOT NECESSARY	80.00	-
1	FAN MOTOR (WCP)	NOT NECESSARY	720.00	-
1	FRONT BONNET (WCP)	BENT	820.00	820.00
2	FRONT BONNET HINGE @\$80EA (WCP)	BENT	160.00	160.00
1	FRONT BONNET LOCK (WCP)	NOT NECESSARY	110.00	-
1	FRONT BONNET INNER TRIM (NPA)	NOT NECESSARY	-	-
1	FRONT BONNET TOP CHROME (WCP)	CRACKED	120.00	120.00
1	FRONT BONNET INNER SEAL (WCP)	NECESSARY	70.00	70.00
1	FRONT BONNET STAND HOLDER (WCP)	CRACKED	30.00	30.00
1	FRONT BONNET CHROME INNER GARNISH (WCP)	DEFORMED	130.00	130.00
	COST PLUS 15%		1,371.00	661.50
			10,511.00	5,071.50

Report Ref No. CS/LPC23002306/Rny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NOT NECESSARY	35.00	-
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			70.00	35.00
	<u>LABOUR</u>			
	TO REMOVE, REPAIR, REPLACE & INSTALL FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,000.00	600.00
	TO R & R AIR CON SYSTEM. TO REFILL & TOP UP AIR CON GAS.	NOT NECESSARY	150.00	-
	TO R & R FRONT RADIATOR.	NOT NECESSARY	120.00	-
	TO R & R WIRING.		60.00	30.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	700.00
			2,330.00	1,330.00
GRAND TOTAL			12,911.00	6,436.50
RECOMMENDED COST OF REPAIRS				6,436.50
LESS EXCESS				-500.00
NETT LIABILITY				5,936.50

Report Ref No. CS/LPC23002306/Rny3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.