

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002309/WVP3E2**Date:** 29/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00159692201

**Claimant Vehicle
No :** SKJ4578R**Insured Vehicle
No :** SNA9563L

Date of Loss: 23/02/2023

Nature of Claim: TP

Claim
No: SNM23D201469/C04/KHONGLHDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKJ4578R**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZY014664

Reg. Date: 01/12/2009 (Man. Year: 2009)

Chassis No: MR053HY9305143492

Colour: Beige

Odometer: 492359 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Kinforest 6 mm

Rear Left Side: Kinforest 6 mm

Front Right Side: Kinforest 6 mm

Rear Right Side: Kinforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,350.00	2,297.72	5,052.28	68.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,480.00	2,840.00	65.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,670.00	3,777.72	7,892.28	67.63
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	11,670.00	3,000.00	8,670.00	74.29
+ GST 8.00/8.00% (S\$)	933.60	240.00	693.60	74.29
Nett Amount (S\$)	12,603.60	3,240.00	9,363.60	74.29

INSPECTION

Date of Assignment: 03/03/2023

Date Inspected: 06/03/2023 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI
BUKIT
Singapore 415675

Estimated Period of Repair: 5.0 days

Adjuster: Mohdakid**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ4578R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	850.00 F	*641.20 FL
2	1		*FRONT BUMPER RETAINER (2PCS)	Cracked (1Pc Only)	180.00 F	*45.10 FL
3	1		*FRONT LIGHT SUPPORT BRACKET - LEFT	No such part	125.00 F	*- FL
4	1		*FRONT LIGHT SUPPORT BRACKET - R	No such part	125.00 F	*- FL
5	1		*FRONT MIDDLE CHROME }	Cracked	280.00 F	*286.00 FL
6	1		*FRONT MIDDLE CHROME SILVING LINNING }		150.00 F	*- FL
7	1		*FRONT LOWER GRILLE	Cracked	220.00 F	*140.00 FL
8	1		*NUMBER PLATE HOLDER	Bent	100.00 F	*50.00 FL
9	1		*FOGLAMP - LEFT	Not Necessary	250.00 F	*- FL
10	1		*FOGLAMP COVER - LEFT	Cracked	180.00 F	*103.00 FL
11	1		*FOGLAMP - RIGHT	Not Necessary	250.00 F	*- FL
12	1		*FOGLAMP COVER - RIGHT	Not Necessary	180.00 F	*- FL
13	1		*REINFORCEMENT	Dented	480.00 F	*380.00 FL
14	2		*REINFORCEMENT 2 SUPPORT	Repair	360.00 F	*- FL
15	1		*FRONT SUPPORT PANEL - TOP	Repair	550.00 F	*- FL
16	1		*FRONT LOWER SUPPORT - LOWER	Repair	380.00 F	*- FL
17	2		*FRONT PANEL SIDE HOLDER BRACKET	Repair	300.00 F	*- FL
18	1		*AIR DUCT TRIM COVER (2PCS)	Damaged (1Pc Only)	240.00 F	*120.00 FL
19	1		*FRONT BUMPER GUIDE TRIM	Damaged	220.00 F	*140.00 FL
20	1		*CONDENSER	Dented	950.00 F	*950.00 FL
21	1		*TOYOTA LOGO	Necessary	95.00 F	*75.00 FL
22	1		*HORN	Not Necessary	125.00 F	*- FL
23	2		*BONNET HINGE	Not Necessary	200.00 F	*- FL
24	6		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	60.00 FS	*30.00 FS
25	8		*FRONT BONNET INNER BOARD CLIPS	Not Necessary	80.00 FS	*- FS
26	10		*FRONT LOWER CHROME CLIPS	Not Necessary	100.00 FS	*- FS
27	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
28	10		*FRONT MIDDLE CHROME CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*NUMBER PLATE AND CASING	Bent	80.00 FS	*40.00 FS
30	1		*GAS AND COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,350.00	3,030.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	732.58
Total Parts (\$\$)	7,350.00	2,297.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	1,600.00	600.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,500.00	800.00
3	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	120.00	50.00
4	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	80.00	30.00
5	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS	New	350.00	0.00
6	TO BALANCE FRONT RIGHT WHEEL	New	80.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	TO CHECK FRONT HORN AND FOCUS AND FUNCTION	New	80.00	0.00
9	REMOVE AND REPLACE CONDENSER, CHECK LEAKING TOP UP COOLANT / GAS	New	150.00	0.00
10	TO CHECK AIRCON RELATED PARTS LEAKING	New	120.00	0.00
11	TO REMOVE AND CHECK RADIATOR / WATER SYSTEM REALTED LEAKING	New	120.00	0.00
Gross Labour Cost (\$\$)			4,320.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >