3/19/23, 11:57 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS23002312/KVY3Q2

19/03/2023 Date:

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle

SLP5089K

Insured Vehicle No:

SLJ2343C

No: Date of Loss: 01/03/2023 Nature of Claim: ΤP

Claim No:

DMPC2300141H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP5089K**

Make & Model: L15B4532449 HONDA HR-V, 1.5 (A) Engine No:

Reg. Date: JHMRU1810GX202450 07/06/2017 (Man. Year: 2017) Chassis No:

Colour: Metallic Dark Blue Odometer: 88785 km

Engine Capacity: Market Value/New Car

N/A

1496 cc

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 215/60 R16 Rear Tyre Size: Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 6,082.40 | 2,254.16 | 3,828.24 | 62.94 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 2,350.00 | 1,520.00 | 830.00 | 35.32 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 8,432.40 | 3,774.16 | 4,658.24 | 55.24 |
| | Approved Total (Overridden) (S\$) | | 3,000.00 | | |
| | Nett Amount (S\$) | 8.432.40 | 3.000.00 | 5,432,40 | 64.42 |

INSPECTION

Date of Assignment: 03/03/2023

Guan Motor Works (HQ)

Date Inspected: 09/03/2023 Inspected At: 176 Sin Ming Drive #02-03 Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Mar 2023)

Parts: M1-SUV HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP5089K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | . Particulars | Condition | Repairer's | Amount |
|-------|---------|-------------|--|-----------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Repair | 829.60 F | *- FN |
| 2 | 1 | | *REAR LH CORNER COVER | Mtg Cracked | 271.80 F | *271.80 FN |
| 3 | 1 | | *REAR LH CORNER COVER RETAINER | Distorted | 18.00 F | *18.00 FN |
| 4 | 1 | | *REAR LH FENDER LOWER WHEEL ARCH GARNISH | Buckled | 198.80 F | *198.80 FN |
| 5 | 1 | | *SET REAR LH FENDER LOWER WHEEL ARCH GARNISH CLIPS | Necessary | 40.00 F | *40.00 FN |
| 6 | 1 | | *REAR LH FENDER UNDER SPLASH SHIELD | Cracked | 98.40 F | *98.40 FN |
| 7 | 1 | | *SET REAR FENDER UNDER SPLASH SHIELD CLIPS | Necessary | 40.00 F | *40.00 FN |
| 8 | 1 | | *REAR LH DOOR | Bent | 955.10 F | *955.10 FN |
| 9 | 1 | | *REAR LH DOOR BLACK STICKER | Necessary | 21.00 F | *21.00 FN |
| 10 | 1 | | *REAR LH DOOR WEATHERSTRIP | Serviceable | 48.80 F | *- FN |
| 11 | 1 | | *SET REAR LH DOOR INNER TRIM BOARD CLIPS | Not Necessary | 60.00 F | *- FN |
| 12 | 1 | | *LH ROCKER PANEL OUTER SPOILER | Serviceable | 408.60 F | *- FN |
| 13 | 1 | | *REAR LH SPORT RIM | Dented | 833.00 F | *833.00 FN |
| 14 | 1 | | *REAR LH SHOCK ABSORBER | Serviceable | 271.80 F | *- FN |
| 15 | 1 | | *REAR LH WHEEL HUB & BEARING | Bent | 341.60 F | *341.60 FN |
| 16 | 1 | | *REAR LOWER AXLE BEAM | Serviceable | 1,645.90 F | *-FN |
| F=Fra | anchise | part. N=Net | ttltemDisc. | | P | |
| | | | | Sub Total (S\$) | 6 N82 4N | 2 817 70 |

Sub Total (\$\$) 6,082.40 2,817.70
- Nett Item Discount on N Items 0.00/20.00% (\$\$) 0.00 563.54

Total Parts (S\$) 6,082.40 2,254.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|--------------|------------|----------|
| <u>Lab</u> | <u>our Items</u> | | | |
| 1 | LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES | New | 800.00 | 500.00 |
| 2 | TO PUTTY AND SPRAY SPRAY PAINTING CHARGES | New | 1,000.00 | 800.00 |
| 3 | TO CHECK WIRING | New | 30.00 | 20.00 |
| 4 | TO REMOVE,REFIX REAR LH DOOR FITTINGS | New | 80.00 | 60.00 |
| 5 | TO REMOVE,REFIX REAR LH UNDER CARRIAGE DAMAGES | New | 280.00 | 50.00 |
| 6 | TO CONDUCT COMPUTERLISE WHEEL ALIGNMENT TEST | New | 80.00 | 60.00 |
| 7 | TO SUPPLY AND APPLY ANTI RUST TREATMENT | New | 80.00 | 30.00 |
| | Gross Labou | r Cost (S\$) | 2,350.00 | 1,520.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >