



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3540G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,050.10	745.00
2	FRONT BUMPER SIDE RETAINER	N/S CRACKED	144.40	72.20
1	FRONT BUMPER FOG LAMP LH	CRACKED	456.70	165.00
1	FRONT BUMPER FOG LAMP GARNISH LH	CRACKED	126.20	126.20
1	FRONT BUMPER LOWER DIFFUSER	SERVICEABLE	485.60	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	486.10	-
1	HEAD LAMP LH	CRACKED	2,145.90	1,800.00
1	HEAD LAMP LOWER BRACKET LH	CRACKED	76.10	76.10
1	FRONT GRILLE	SERVICEABLE	582.30	-
1	FRONT GRILLE EMBLEM LOGO	SERVICEABLE	89.10	-
1	FRONT GRILLE SIDE BRACKET	CRACKED	87.30	-
1	FRONT GRILLE BASE	SERVICEABLE	413.60	-
1	FRONT GRILLE MOULDING	SERVICEABLE	368.10	-
1	FRONT FENDER LH	SERVICEABLE	756.10	-
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	134.20	-
1	FRONT FENDER EMBLEM HYBRID LH	SERVICEABLE	117.40	-
1	FRONT FENDER ARCH GARNISH LH	CRACKED / DEFORMED	128.90	128.90
1	FRONT SUPPORT PANEL	SERVICEABLE	898.10	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	185.10	-
	LESS 20% DISCOUNT		-1,746.26	-622.68
			6,985.04	2,490.72
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	SET FRONT BUMPER CLIPS (SN)	CRACKED / DEFORMED	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	15.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	15.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	15.00
			300.00	75.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK THE WIRING SYSTEM TO FACILITATE THE REPAIR AND REFIT THE SAME.		100.00	30.00
	DIAGNOSTIC & RESET FAULT CODE.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT THE RADIATOR AND CONDUCT A PRESSURE TEST.	NOT NECESSARY	200.00	-
	REMOVE AND REFIT THE AIR CONDENSER AND REFILL THE AIRCON GAS.	NOT NECESSARY	200.00	-
	TO REMOVE, RENEW AND REFIT ALL ACCIDENT-DAMAGED PARTS. CUT, WELD, PANEL BEAT, AND STRAIGHTEN ALL ACCIDENT DAMAGE AREAS AND FIT THE ABOVE SAME.		300.00	200.00
	TO SPRAY ANTI-RUST ON ACCIDENT-AFFECTED PANEL.	NOT NECESSARY	100.00	-
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT-AFFECTED AREAS.		1,000.00	300.00
			2,200.00	530.00
GRAND TOTAL			9,485.04	3,095.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS3/SPF22012407/Dvy3e2-1

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,450-\$3,000

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.